

## Universal Process Calibrator MCS-XV





EM0256-06

#### **IMPORTANT INSTRUCTIONS:**

- Keep the calibrator in a dry environment whenever possible.
- The fuse which protects the current measurement circuit, code 01.02.0277-21, is a special part. So, only replace the fuse by another original from factory.
- In case of failure, contact Presys Technical Assistance.
- When not in daily use, before starting up, let the calibrator be turned on for at least one hour.

The warranty conditions are available on our site: www.presys.com.br/warranty

### Table of contents

| 1 - INTRODUCTION  | 1  |
|---|----|
| 1.1. General Description                                    | 1  |
| 1.2. Specifications – Inputs                                | 2  |
| 1.3. Specifications – Outputs                               | 5  |
| 1.4. Optional Items   | 8  |
| 1.5. General Specifications                                 | 10 |
| 1.6. Special Software Features                              | 13 |
| 1.7. Order Code   |    |
| 2 - Operation   | 15 |
| 2.1. Parts Identification                                   |    |
| 2.2. Battery and Charger (only for MCS-XV Portable Version) | 20 |
| 2.3. Using MCS-XV: Basic Functions                          | 22 |
| 2.4. Calibrator   |    |
| 2.4.1. Measurement or Input Functions                       |    |
| 2.4.2. Generation or Output Functions                       |    |
| 2.4.3. Available Power Supplies                             |    |
| 2.4.4. Input Special Functions                              |    |
| 2.4.5. Output Special Functions                             |    |
| 2.4.6. Saving Current Configuration (Memory Manager)        |    |
| 2.4.7. AD/Ratio   |    |
| 2.4.8. Bar Graph  |    |
| 2.4.9. Calibration Examples                                 |    |
| 2.5. HART <sup>®</sup> Connections                          |    |
| 2.5.2. Starting Communication                               |    |
|   |    |

| 2.5.3. Adjusting the Measurement Range of a HART® Transmitter (CH Option)                | 62  |
|--|-----|
| 2.5.4. Adjusting the Measurement Range of a HART® Transmitter with Reference (CH Option) | 63  |
| 2.5.5. Checking / Adjusting HART <sup>®</sup> Transmitter mA Output (CH Option).         | 66  |
| 2.5.6. Full-Hart Configurator (FH Option)  | 67  |
| 2.6. Data Logger   | 72  |
| 2.7. Automatic Tasks   | 74  |
| 2.7.1. Creating Tasks  | 74  |
| 2.7.2. Performing Tasks  | 77  |
| 2.7.3. Viewing Results   | 79  |
| 2.8. Help Desk   | 82  |
| 3 - SETTINGS   |     |
| 3.1. Date and Time   |     |
| 3.2. Network   |     |
| 3.3. Services  |     |
| 3.3.1 Web Server   |     |
| 3.3.2 Remote access - VNC  |     |
| 3.3.3 SCPI Command List  |     |
| 3.3.4 System   |     |
| 4 - Adjustment   |     |
| 4.1. Input adjustment (IN)   |     |
| 4.2. Output Adjustment (OUT)   |     |
| 4.3. Pressure Calibration  |     |
| 5 - Maintenance  |     |
| 5.1. Replacing Battery (only for MCS-XV Portable)  | 99  |
| 5.2. Replacing Current Input Fuse  |     |
| 6 - Pressure Units Conversion  | 103 |
| Notes  | 104 |

#### **1 - INTRODUCTION**

#### **1.1. General Description**

**MCS-XV** Process Calibrator enables measurement and generation of signals used in instrumentation and process control. Provides all features required for easier calibration and adjustment services on process instruments. It has high levels of accuracy, including aspects relating to changes in room temperature and maintains the specifications over long periods of time.

Designed for field use, includes useful items as: carrying case, holders with fastener rings or belts for a hands-free operation, 5.7" display with LED backlight for a better viewing in poor lighting conditions, rechargeable battery and large memory capacity to store the values obtained during calibrations enabling the transfer of these to the PC when needed. In addition, several constructive features that add quality and efficiency to MCS-XV, allowing its on-field and workbench use (**RM** Version – 19" Rack Mounting, **DT** Version – Desktop).

Incorporates state-of-the-art concepts of automatic calibration and adjustment via computer. Instrument and computer share measurement data obtained for a more efficient handling of information such as report and certificate issues, automatic work management, data sorting and storage, for an overall coverage of quality procedure requirements, especially those related to ISO-9000.

It has HART® communication for reading and setting parameters of field devices that have this protocol.

Can be supplied with up to four pressure sensors. Thus, a single calibrator can have different ranges of pressure, for example vacuum, 0 to 100 psi, 0 to 1,000 psi and 0 to 3,000 psi, or any combination of available ranges. They can also be purchased with a certain number of sensors, which may be later increased. For pressure sensors increase beyond the available on the calibrator, there is the possibility of acquiring an external pressure module (MPYA) that communicates with the MCS-XV via USB port.

Another optional item is a high accuracy sensor, which among its many functions can work as a standard thermometer. Thus, while indicating the reference temperature, allows the calibration of another temperature sensor.

### 1.2. Specifications – Inputs

|              | Input Ranges                   | Resolution       | Accuracy     | Remarks                    |  |
|--------------|--------------------------------|------------------|--------------|----------------------------|--|
| millivolt    | -500 mV to -150 mV             | 0.01 mV          | ± 0.02 % FS* | $R_{input} > 10 M\Omega$   |  |
|              | -150 mV to 150 mV              | 0.001 mV         | ± 0.01 % FS  | auto-ranging               |  |
|              | 150 mV to 2450 mV              | 0.01 mV          | ± 0.02 % FS  |                            |  |
| volt         | -10 V to 11 V                  | 0.0 <b>001</b> V | ± 0.02 % FS  | R <sub>input</sub> > 1 MΩ  |  |
|              | 11 V to 45 V                   | 0.0001 V         | ± 0.02 % FS  |                            |  |
| mA           | -5 mA to 24.5 mA               | 0.0001 mA        | ± 0.01 % FS  | Rinput < 120 Ω             |  |
| resistance   | 0 to 400 Ω                     | 0.01 Ω           | ± 0.01 % FS  | Excitation current 0.85    |  |
|              | 400 to 2500 Ω                  | 0.01 Ω           | ± 0.03 % FS  | mA, auto-ranging           |  |
| frequency ** | 0 to 600 Hz                    | 0.01 Hz          | ± 0.04 Hz    | $R_{input} > 50 \ k\Omega$ |  |
|              | 600 to 1300 Hz                 | 0.1 Hz           | ± 0.2 Hz     | Voltage DC max = 30 V      |  |
|              | 1300 to 5000 Hz                | 1 Hz             | $\pm$ 2 Hz   | AC Signal from 0.3 to 30 V |  |
|              |                                |                  |              | auto-ranging               |  |
| counter **   | 0 to 10 <sup>8</sup> – 1 count | 1 count          |              | Same as frequency. Pulse   |  |
|              |                                |                  |              | frequency < 3000 Hz        |  |

(\*) FS = Full Scale.

(\*\*) Function available since the frequency output is not configured.

|         | Input Ranges                      | Resolution        | Accuracy                    | Remarks    |
|---------|-----------------------------------|-------------------|-----------------------------|------------|
| Pt-100  | -200 to 850 °C / -328 to 1562 °F  | 0.01 °C / 0.01 °F | <u>± 0.1 °C / ± 0.2</u> °F  | IEC 60751  |
| Pt-1000 | -200 to 400 °C / -328 to 752 °F   | 0.1 °C / 0.1 °F   | ± 0.1 °C / ± 0.2 °F         | IEC 60751  |
| Cu-10   | -200 to 260 °C / -328 to 500 °F   | 0.1 °C / 0.1 °F   | ± 2.0 °C / ± 4.0 °F         | Minco 16-9 |
| Ni-100  | -60 to 250 °C / -76 to 482 °F     | 0.1 °C / 0.1 °F   | ± 0.2 °C / ± 0.4 °F         | DIN-43760  |
| Probe*  | -200 to 850 °C / -328 to 1562 °F  | 0.01 °C / 0.01 °F | ± 0.1 °C / ± 0.2 °F         | IEC 60751  |
| TC-J    | -210 to 1200 °C / -346 to 2192 °F | 0.1 °C / 0.1 °F   | ± 0.2 °C / ± 0.4 °F         | IEC 60584  |
| тс-к    | -270 to -150 °C / -454 to -238 °F | 0.1 °C / 0.1 °F   | $\pm$ 0.5 °C / $\pm$ 1.0 °F | IEC 60584  |
| ТС-К    | -150 to 1370 °C / -238 to 2498 °F | 0.1 °C / 0.1 °F   | $\pm$ 0.2 °C / $\pm$ 0.4 °F | IEC 60584  |
| тс-т    | -260 to -200 °C / -436 to -328 °F | 0.1 °C / 0.1 °F   | $\pm$ 0.6 °C / $\pm$ 1.2 °F | IEC 60584  |
| тс-т    | -200 to -75 °C / -328 to -103 °F  | 0.1 °C / 0.1 °F   | $\pm$ 0.4 °C / $\pm$ 0.8 °F | IEC 60584  |
| тс-т    | -75 to 400 °C / -103 to 752 °F    | 0.1 °C / 0.1 °F   | $\pm$ 0.2 °C / $\pm$ 0.4 °F | IEC 60584  |
| тс-в    | 50 to 250 °C / 122 to 482 °F      | 0.1 °C / 0.1 °F   | $\pm$ 2.5 °C / $\pm$ 5.0 °F | IEC 60584  |
| тс-в    | 250 to 500 °C / 482 to 932 °F     | 0.1 °C / 0.1 °F   | $\pm$ 1.5 °C / $\pm$ 3.0 °F | IEC 60584  |
| тс-в    | 500 to 1200 °C / 932 to 2192 °F   | 0.1 °C / 0.1 °F   | $\pm$ 1.0 °C / $\pm$ 2.0 °F | IEC 60584  |
| тс-в    | 1200 to 1820 °C / 2192 to 3308 °F | 0.1 °C / 0.1 °F   | $\pm$ 0.7 °C / $\pm$ 1.4 °F | IEC 60584  |

(\*) Probe is an input for a reference RTD in order to use as standard thermometer. The accuracy is related only to MCS-XV.

| Input Ranges                           | Resolution      | Accuracy                    | Remarks       |
|--|-----------------|-----------------------------|---------------|
| TC-R -50 to 300 °C / -58 to 572 °F     | 0.1 °C / 0.1 °F | ± 1.0 °C / ± 2.0 °F         | IEC 60584     |
| TC-R 300 to 1760 °C / 572 to 3200 °F   | 0.1 °C / 0.1 °F | ± 0.7 °C / ± 1.4 °F         | IEC 60584     |
| TC-S -50 to 300 °C / -58 to 572 °F     | 0.1 °C / 0.1 °F | ± 1.0 °C / ± 2.0 °F         | IEC 60584     |
| TC-S 300 to 1760 °C / 572 to 3200 °F   | 0.1 °C / 0.1 °F | ± 0.7 °C / ± 1.4 °F         | IEC 60584     |
| TC-E -270 to -150 °C / -454 to -238 °F | 0.1 °C / 0.1 °F | ± 0.3 °C / ± 0.6 °F         | IEC 60584     |
| TC-E -150 to 1000 °C / -238 to 1832 °F | 0.1 °C / 0.1 °F | ± 0.1 °C / ± 0.2 °F         | IEC 60584     |
| TC-N -260 to -200 °C / -436 to -328 °F | 0.1 °C / 0.1 °F | ± 1.0 °C / ± 2.0 °F         | IEC 60584     |
| TC-N -200 to -20 °C / -328 to -4 °F    | 0.1 °C / 0.1 °F | $\pm$ 0.4 °C / $\pm$ 0.8 °F | IEC 60584     |
| TC-N -20 to 1300 °C / -4 to 2372 °F    | 0.1 °C / 0.1 °F | $\pm$ 0.2 °C / $\pm$ 0.4 °F | IEC 60584     |
| TC-L -200 to 900 °C / -328 to 1652 °F  | 0.1 °C / 0.1 °F | $\pm$ 0.2 °C / $\pm$ 0.4 °F | DIN-43710     |
| TC-C 0 to 1500 °C / 32 to 2732 °F      | 0.1 °C / 0.1 °F | ± 0.5 °C / ± 1.0 °F         | W5Re / W26Re  |
| TC-C 1500 to 2320 °C / 2732 to 4208 °F | 0.1 °C / 0.1 °F | $\pm$ 0.7 °C / $\pm$ 1.4 °F | W5Re / W 26Re |

V

### 1.3. Specifications – Outputs

|                             | Output Ranges                       | Resolution        | Accuracy                    | Remarks  |
|-----------------------------|-------------------------------------|-------------------|-----------------------------|--|
| millivolt                   | -10 mV to 110 mV                    | 0.001 mV          | ± 0.02 % FS                 | Rout < 0.3 Ω   |
| volt                        | -0.5 V to 12 V                      | 0.0001 V          | ± 0.02 % FS                 | Rout < 0.3 Ω   |
| mA                          | 0 to 24 mA                          | 0.0001 mA         | ± 0.02 % FS                 | R <sub>max</sub> = 700 Ω   |
| (XTR) 2-wire<br>Transmitter | 4 mA to 24 mA                       | 0.0001 mA         | ± 0.02 % FS                 | V <sub>max</sub> = 60 V  |
| Resistance                  | 0 to 400 Ω<br>400 to 2500 Ω         | 0.01 Ω<br>0.1 Ω   | ± 0.02 % FS<br>± 0.03 % FS  | For external excitation current of 1.0 mA                              |
| Frequency*                  | 0 to 100 Hz<br>0 to 10000 Hz        | 0.01 Hz<br>1 Hz   | ± 0.02 Hz<br>± 2 Hz         | Peak value:<br>22 V / 25 mA max.                                       |
| Pulse*                      | 0 to 10 <sup>8</sup> – 1 pulses     | 1 pulse           |                             | Peak value:<br>22 V / 25 mA max.<br>Pulses frequency up<br>to 10000 Hz |
| Pt-100                      | -200 to 850 °C / -328 to 1562 °F    | 0.01 °C / 0.01 °F | $\pm$ 0.2 °C / $\pm$ 0.4 °F | IEC 60751  |
| Pt-1000                     | -200 to 400 °C / -328 to 752 °F     | 0.1 °C / 0.1 °F   | $\pm$ 0.1 °C / $\pm$ 0.2 °F | IEC 60751  |
| Cu-10                       | -200 to 260 °C / -328 to 500 °F     | 0.1 °C / 0.1 °F   | $\pm$ 2.0 °C / $\pm$ 4.0 °F | Minco 16-9   |
|                             | -60 to 250 °C / -76 to 482 °F       | 0.1 °C / 0.1 °F   | $\pm$ 0.2 °C / $\pm$ 0.4 °F | DIN-43760  |
| (*) Function ava            | ilable since the frequency input is | not configured.   |                             |  |

| Output Ranges                                 | Resolution             | Accuracy                    | Remarks   |
|---|------------------------|-----------------------------|-----------|
| TC-J -210 to 1200 °C / -346 to 2192 °F        | 0.1 °C / 0.1 °F        | ± 0.4 °C / ± 0.8 °F         | IEC 60584 |
| <b>TC-K</b> -270 to -150 °C / -454 to -238 °F | 0.1 °C / 0.1 °F        | ± 1.0 °C / ± 2.0 °F         | IEC 60584 |
| TC-K -150 to 1370 °C / -238 to 2498 °F        | 0.1 °C / 0.1 °F        | ± 0.4 °C / ± 0.8 °F         | IEC 60584 |
| TC-T -260 to -200 °C / -436 to -328 °F        | 0.1 °C / 0.1 °F        | ± 1.2 °C / ± 2.4 °F         | IEC 60584 |
| TC-T -200 to -75 °C / -328 to -103 °F         | 0.1 °C / 0.1 °F        | ± 0.8 °C / ± 1.6 °F         | IEC 60584 |
| TC-T -75 to 400 °C / -103 to 752 °F           | <u>0.1 °C / 0.1 °F</u> | ± 0.4 °C / ± 0.8 °F         | IEC 60584 |
| <b>TC-B</b> 50 to 250 °C / 122 to 482 °F      | 0.1 °C / 0.1 °F        | ± 5.0 °C / ± 10.0 °F        | IEC 60584 |
| TC-B 250 to 500 °C / 482 to 932 °F            | 0.1 °C / 0.1 °F        | $\pm$ 3.0 °C / $\pm$ 6.0 °F | IEC 60584 |
| TC-B 500 to 1200 °C / 932 to 2192 °F          | 0.1 °C / 0.1 °F        | $\pm$ 2.0 °C / $\pm$ 4.0 °F | IEC 60584 |
| TC-B 1200 to 1820 °C / 2192 to 3308 °F        | 0.1 °C / 0.1 °F        | ± 1.4 °C / ± 2.8 °F         | IEC 60584 |
| <b>TC-R</b> -50 to 300 °C / -58 to 572 °F     | 0.1 °C / 0.1 °F        | ± 2.0 °C / ± 4.0 °F         | IEC 60584 |
| TC-R 300 to 1760 °C / 572 to 3200 °F          | 0.1 °C / 0.1 °F        | ± 1.4 °C / ± 2.8 °F         | IEC 60584 |
| TC-S -50 to 300 °C / -58 to 572 °F            | 0.1 °C / 0.1 °F        | $\pm$ 2.0 °C / $\pm$ 4.0 °F | IEC 60584 |
| TC-S 300 to 1760 °C / 572 to 3200 °F          | 0.1 °C / 0.1 °F        | ± 1.4 °C / ± 2.8 °F         | IEC 60584 |
| TC-E -270 to -150 °C / -454 to -238 °F        | 0.1 °C / 0.1 °F        | $\pm$ 0.6 °C / $\pm$ 1.2 °F | IEC 60584 |
| TC-E -150 to 1000 °C / -238 to 1832 °F        | 0.1 °C / 0.1 °F        | ± 0.2 °C / ± 0.4 °F         | IEC 60584 |

| Output Ranges                            | Resolution      | Accuracy                    | Remarks       |
|--|-----------------|-----------------------------|---------------|
| TC-N -260 to -200 °C / -436 to -328 °F   | 0.1 °C / 0.1 °F | ± 2.0 °C / ± 4.0 °F         | IEC 60584     |
| TC-N -200 to -20 °C / -328 to -4 °F      | 0.1 °C / 0.1 °F | ± 0.8 °C / ± 1.6 °F         | IEC 60584     |
| TC-N -20 to 1300 °C / -4 to 2372 °F      | 0.1 °C / 0.1 °F | ± 0.4 °C / ± 0.8 °F         | IEC 60584     |
| TC-L -200 to 900 °C / -328 to 1652 °F    | 0.1 °C / 0.1 °F | $\pm$ 0.4 °C / $\pm$ 0.8 °F | DIN-43710     |
| <b>TC-C</b> 0 to 1500 °C / 32 to 2732 °F | 0.1 °C / 0.1 °F | ± 0.5 °C / ± 1.0 °F         | W5Re / W26Re  |
| TC-C 1500 to 2320 °C / 2732 to 4208 °F   | 0.1 °C / 0.1 °F | ± 0.7 °C / ± 1.4 °F         | W5Re / W 26Re |

7

Accuracy values are valid within one year and temperature range of 20 to 26 °C. Outside these limits add 0.001 % FS / °C taking 23 °C as the reference temperature. For thermocouples, using the internal cold junction compensation add a cold junction compensation error of  $\pm$  0.2 °C or  $\pm$  0.4 °F max.

#### 1.4. Optional Items

#### **Pressure Sensors**

Can be placed up to 4 pressure sensors in MCS-XV, with ranges between 250 mmH<sub>2</sub>O and 10,000 psi.

| Ranges *            | Resolution | Accuracy      | Remarks                               |
|---------------------|------------|---------------|---------------------------------------|
| (0) 0 – 25 mbar     | 0.0001     | ± 0.05 % FS** | Gage pressure.                        |
| (1) 0 – 70 mbar     | 0.001      | ± 0.05 % FS   | Used with air or inert                |
| (2) 0 – 350 mbar    | 0.01       | ± 0.025 % FS  | gases.                                |
| (3) 0 – 1 bar       | 0.00001    | ± 0.025 % FS  |                                       |
| (4) 0 – 2 bar       | 0.00001    | ± 0.025 % FS  | Gage or absolute pressure.            |
| (5) 0 – 7 bar       | 0.0001     | ± 0.025 % FS  | Used with fluids                      |
| (6) 0 – 20 bar      | 0.0001     | ± 0.025 % FS  | (gases or liquids)<br>compatible with |
| (7) 0 – 35 bar      | 0.001      | ± 0.025 % FS  | INOX 316 L stainless steel.           |
| (8) 0 – 70 bar      | 0.001      | ± 0.025 % FS  |                                       |
| (9) 0 – 210 bar     | 0.001      | ± 0.025 % FS  |                                       |
| (10) 0 – 350 bar    | 0.01       | ± 0.025 % FS  |                                       |
| (11) 0 – 700 bar    | 0.01       | ± 0.05 % FS   |                                       |
| (12) Others upon re | equest     |               |                                       |

(\*) Gage pressure, absolute pressure (from range 3 to 8), vacuum (only for range 3), compound (from range 3 to 8), and differential (from range 0 to 2). (\*\*) FS = Full Scale.

The differential sensor occupies two pressure outlets.

#### Note: Optional BR (Barometric Reference - 1 barA)

Sensor for ambient pressure measurement. Can be used for simulated indication of absolute pressure on the other sensors. Accuracy:  $\pm 0.02$  % FS (1 bar).

Pressure accuracy values are valid within one year and temperature range of 20 to 26 °C. Outside these limits add 0.005 % FS/ °C taking 23 °C as the reference temperature. These values are obtained through algorithms of temperature compensation on pressure measurements.

#### Probe

Probe is a high accuracy 4-wire Pt100 available under ordering. The calibrator input accepts Callendar-Van Dusen and ITS-90 curve correction coefficients.

#### **MPYA Pressure Module**

Optional independent pressure measurement module. The MPYA communicates with the MCS-XV which performs pressure indication. See MPYA specifications on the Presys website.



#### **1.5. General Specifications**

RTD input for 2, 3 and 4 wires. Table IEC 60751, Callendar-Van Dusen or ITS-90 user-configurable.

Regulated transmitter power supply (TPS): 24 Vdc, with protection for short circuit (30 mA).

Contact input for calibration of switches (pressure switch, thermo switch etc.).

50 Vdc in/out insulation.

Five minutes warm-up time.

Operating temperature range: 0 to 50 °C.

Relative Humidity: 0 to 90 % RH.

Pneumatic Connection: 1/4" NPTF (1/8" NPTF only for the range 0 – 10,000 psi or above).

Overpressure: up to twice the sensor full scale pressure (for sensors up to 5,000 psi).

Engineering units - Temperature: °C, °F, K. Pressure: psi, bar, mbar, MPa, kPa, Pa, atm, at, mH<sub>2</sub>O, mH<sub>2</sub>O@4°C, mmH<sub>2</sub>O, mmH<sub>2</sub>O@4°C, cmH<sub>2</sub>O@4°C, cmH<sub>2</sub>O@4°C, tH<sub>2</sub>O@4°C, inH<sub>2</sub>O@4°C, inH<sub>2</sub>O@4°C, inH<sub>2</sub>O@60°F, torr, mmHg, mmHg@0°C, cmHg, cmHg@0°C, inHg@0°C, inHg@60°F, gf/cm<sup>2</sup>, kgf/cm<sup>2</sup>, kgf/m<sup>2</sup>.

Built in Web Server, Ethernet communication. USB port or WiFi (with optional adapter)

HART<sup>®</sup> Communication Protocol.

Calibration Certificate (optional).

One-year warranty, except for rechargeable battery.

#### Portable Version (MCS-XV). Designed for field use.

# PRENI calendar balance UNENTI NOS-NO Della Del

Rechargeable battery, up to 8 hours of operation with current output in 12 mA and display brightness set to 50 %.

Includes technical manual, test leads, USB/Micro USB cable, ETHERNET cable, carrying case and battery charger.

Dimensions: 140 mm x 250 mm x 80 mm (HxWxD).

Weight: 1.5 kg approx.

#### Rack Mounting Version (MCS-XV-RM). Designed for mounting on 19" rack or workbench.

Powered from 100 to 240 Vac, 50 / 60 Hz. Includes technical manual, USB cable (A/B), ETHERNET cable and test leads. Dimensions: 132 mm x 483 mm x 250 mm (HxWxD). Weight: 4.0 kg approx.



#### Desktop Version (MCS-XV-DT). Designed for use on workbench.



Powered from 100 to 240 Vac, 50 / 60 Hz. Includes technical manual, USB/Micro USB cable, ETHERNET cable and test leads. Dimensions: 132 mm x 308 mm x 275 mm (HxWxD). Weight: 3.0 kg approx.

#### Notes:

- \* MCS-XV and ISOPLAN® are Presys trademarks.
- \* Changes can be introduced in the instrument, altering specifications in this manual.
- \* HART<sup>®</sup> is a *FieldComm Group* trademark.

#### **1.6. Special Software Features**

#### - Special Functions:

- 1) SCALE: makes the scaling of both input and output.
- 2) CONV: converts any input to any output, galvanically isolated.
- 3) RAMP: increasing or decreasing ramps with configurable ramp time and level mark.
- 4) STEP: steps or setpoints with configurable time.
- Memory Manager: stores configuration types predefined by the user.
- Automated Tasks: creating of calibration work orders and automatic execution of calibration services, storage of data and reporting.
- Data Logger: monitoring of input or output signals, storage and visualization of data in chart or table.
- Help Desk: storage and viewing videos and documents on the calibrator screen.

#### 1.7.

| CS-XV - Calibrator MCS-XV Portable<br>CS-XV+RM - Calibrator MCS-XV Desktop Version<br>CS-XV-DT - Calibrator MCS-XV Desktop Version<br>art Communication<br>H - Hart Calibrator (basic commands: zero, span, trim mA)<br>H - Full-Hart Configurator, with DD library from FieldComm Group.<br>umber os Pressure Inputs<br>• no pressure sensors 3 - three sensors<br>• one sensor 4 - four sensors<br>• two sensors<br>HNGE Input 1 (Only for version with one sensor or more)<br>• cAbsolute (Only for ranges 3 to 8)<br>• Cage (Ranges 0 to 1)<br>• Cage (Ranges 0 to 2)<br>• Cage (Ranges 0 to 1)<br>• Cage (Ranges 0 to 2)<br>• Cage (Ranges 0 to 1)<br>• Cag | der Code                          |                               | ] - [] - [] -            | Ģ-Ģ | - [] - [] | ) - Çi - İ |  |
|--|-----------------------------------|-------------------------------|--------------------------|-----|-----------|------------|--|
| H - Hart Calibrador (basic commands: zero, span, trim mA)<br>H - Full-Hart Configurator, with DD library from FieldComm Group.<br>umber os Pressure Inputs<br>• no pressure sensors 3 - three sensors<br>• one sensor 4 - four sensors<br>• two sensors<br>• two sensors<br>• MGE Input 1 (Only for version with one sensor or more)<br>• Absolute (Only for ranges 3 to 8) C - Compound* (Only for ranges 3 to 8)<br>• Gage (Ranges 0 to 11) D • Differential*** (Only for ranges 0 to 2)<br>• Vacuum (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)<br>• Absolute (Only for version with two sensors or more)   | MCS-XV-RM - Calibrator MCS-XV F   | ack Mounting Version          |                          |     |           |            |  |
| no pressure sensors 3 - three sensors     one sensor 4 - four sensors     two sensors  ANGE Input 1 (Only for version with one sensor or more)     heck table on item 1.4 - Optional Items - Pressure Sensors)  ressure Type Input 1 (Only for version with one sensor or more)     - Absolute (Only for ranges 3 to 8)     C - Compound* (Only for ranges 3 to 8)     Gage (Ranges 0 to 11)     D - Differential*** (Only for ranges 0 to 2)  Vacuum (Only for version with two sensors or more)  ressure Type Input 2**  ANGE Input 3** (Only for version with three sensors or more)  |                                   |                               |                          |     |           |            |  |
| heck table on item 1.4 - Optional Items - Pressure Sensors)  ressure Type Input 1 (Only for version with one sensor or more)  - Absolute (Only for ranges 3 to 8)  C - Compound* (Only for ranges 3 to 8)  - Gage (Ranges 0 to 11)  D - Differential*** (Only for ranges 0 to 2)  - Vacuum (Only for version with two sensors or more)  ressure Type Input 2**  ANGE Input 3** (Only for version with three sensors or more)   |                                   |                               |                          |     |           |            |  |
| Absolute (Only for ranges 3 to 8)     C - Compound* (Only for ranges 3 to 8)     Gage (Ranges 0 to 11)     D - Differential**** (Only for ranges 0 to 2)     Vacuum (Only for version with two sensors or more)  ANGE Input 2** ANGE Input 2** ANGE Input 3** (Only for version with three sensors or more)  |                                   |                               |                          |     |           |            |  |
| ressure Type Input 2**   |                                   | 8) C - Compound*              | (Only for ranges 3 to 8) | 2)  |           |            |  |
| ANGE Input 3** (Only for version with three sensors or more)   | RANGE Input 2** (Only for version | with two sensors or more)     |                          |     |           |            |  |
|  | Pressure Type Input 2**           |                               |                          |     |           |            |  |
|  | RANGE Input 3** (Only for version | with three sensors or more) - |                          |     |           |            |  |
| ressure type input s   | Pressure Type Input 3**           |                               |                          |     |           |            |  |
| ANGE Input 4** (Only for version with four sensors or more)  | RANGE Input 4** (Only for version | with four sensors or more)    |                          |     |           |            |  |
|  | Pressure Type Input 4**           |                               |                          |     |           |            |  |

-

Optional (Only for version with up to three sensors) BR - Barometric Reference (1 barA - Accuracy: 0.2 mbar)

Sensor for ambient pressure measurement. Can be used for simulated indication of absolute pressure on the other sensors.

(\*) From -1 bar to full scale of range (\*\*) Same code as input 1 (\*\*\*) The differential sensor ocupies two pressure outlets.





Fig. 01 - Front Panel - MCS-XV



#### How to Use the MCS-XV Carrying Case






Fig. 03 - How to Use the Carrying Case

Accessories: The bag has three compartments; one for accommodate the calibrator and the others to hold various accessories including test leads, adapter for connecting thermocouple wires, spare fuse, handles for transport and field use and technical manual.

**Optional items:** MCS-XV optional items are the accurate temperature sensor (PROBE), the Pressure Module (MPYA), the block of external cold junction compensation of high accuracy, pressure sensors and ISOPLAN<sup>®</sup> software. The optional items are described in specific manuals.



### MCS-XV-DT (Desktop Version)



#### 2.2. Battery and Charger (only for MCS-XV Portable Version)

20

The MCS-XV is supplied with rechargeable battery which enables up to 10 hours of continuous use. This autonomy is reduced according to the active functions. A battery charger that can be plugged into power supply from 100 to 240 Vac is included. The time for full charge is 3 hours.

The battery level is displayed in the main menu, as shown below.



Fig. 06 - Main Menu



Low Battery Level, charging required



Charging Battery

#### Fig. 07 - Battery Levels

Clicking on the battery icon, the following screen is shown. This screen shows the battery power (in percent), current (positive value if the battery is charging, negative if it is not) and the estimated time of instrument autonomy based on the current consumption.



Fig. 08 - Battery Status

The charger provides the battery charge while it feeds the calibrator, thus permitting the calibrator to be used normally while the battery is being charged.

The batteries used by the calibrator are made of Lithium Polymer (Li-Po). This new technology for rechargeable batteries does not have the undesirable characteristics of memory effect as their preceding batteries made of Nickel Cadmium (Ni-Cd).

To prevent explosion or fire, use only the battery charger supplied by Presys. Do not short circuit or damage the battery.

#### 2.3. Using MCS-XV: Basic Functions

When powered on, the calibrator goes through a self-test routine and shows the last adjustment date. In case of failure, it displays a message to indicate error; if that occurs, the instrument should be sent to manufacturer for repair.

After the self-test is completed, the display shows the main menu, as showed in Figure 06.

The main menu is divided into 06 functions:

CALIBRATOR – selects the input/output functions, see section 2.4.

HART<sup>®</sup> – optional module that allows communication with devices that have Hart<sup>®</sup> protocol, see section 2.5.

**SETTINGS** – general instrument settings, see section 3.

TASKS – performs calibrations automatically, see section 2.7.

DATA LOGGER - record measurements, enabling visualization in chart or table, see section 2.6.

**HELP DESK** – features videos made by Presys to assist in the use of the calibrator, and can also store videos and documents made by the user, see section 2.9.

#### 2.4. Calibrator

To select the input or output functions, from the main menu, press the **CALIBRATOR** button. The following screen is displayed.




Fig. 09 - Calibrator Functions

At the top is shown the channel 1 and at the bottom the channel 2. It can be changed in **Layout** option on Quick Navigator menu.

The icon shows a **Quick Navigator**, with the options for Main Menu (**HOME**), **Data-Logger**, **Tasks** and an option to enable the **CH-2** (Channel 2). Pressing **MORE OPTIONS**, there are options for the selection of display

Layout, Memory Manager (see section 2.4.6), AD/RATIO (see section 2.4.7) and BARGRAPH (see section 2.4.8). Furthermore, it brings information about the input/output configuration and IP address. Press BACK to return to Calibrator Mode or HOME to go to Main Menu.



Fig. 10 - Quick Navigator and Secondary Menu


The channel 1 can be configured only as an input. The channel 2 can be configured as an output (default setting) or as PROBE or PRESSURE input. An example of channel 2 used as input is the calibration of a pressure transmitter, when you want to measure the transmitter current (mA input on CH-1) and the pressure (PRESSURE input in CH-2). To enable channel 2 as input, press the icon and enable the CH-2 option. To enable channel 2 as output disable CH-2 option. To return to the Calibrator screen press the **BACK** button. To go to the main menu, press the **HOME** button.

#### 2.4.1. Measurement or Input Functions

#### a) Input Type Configuration

Press **Input CH-1**, select through the menu the type of signal to be measured and use the corresponding terminals (see **Figure 17 – Input Connections** or press the **HELP** button).





For OHM measurement, you should also select between 2, 3 or 4 wires options.

In **FREQ.** option, you can select the frequency or counter input. For counter input must also set the time (in seconds). If time is zero there is a continuous count of pulses received at the input. If the value is not zero, the count is done only during this time (window). The count starts immediately after pressing the **OK** button.

For **RTD** input, you must choose the standard table type used, the number of lead wires (2, 3 or 4 wires) and the temperature scale (ITS-90 or IPTS-68). You can also set the Callendar-Van Dusen or ITS-90 sensor coefficients by selecting the CVD or ITS-90 option and the desired curve from the ID list. To create new CVD or ITS-90

coefficients or edit existing ones, select between the two options and press the edit button  $\square > ADD$ . The curves you create appear in the list ordered by the ID. Select CONFIGURATION to enter an ID or tag for the sensor in ID and inform the sensor range in MIN and MAX. Select PARAMETERS to enter the sensor curve, usually informed on the sensor calibration certificate.

#### For Callendar-Van Dusen:

26

Fill in the value of R0 (Resistance at 0 °C) and the parameters A, B and C together with their exponents.




Fig. 12 - Callendar-Van Dusen Coefficient Configuration

#### For ITS-90:

Fill in the value of RPTW (Resistance at 0.01 °C) and select the range for negative and / or positive curve before entering the parameters together with their exponents.




Fig. 13 - ITS-90 Coefficient Configuration

**Negative Range:** Accesses the coefficients to be used for temperatures below or equal to the triple point of water (0.01 °C).

| Recommend | ded Temperature Range (Negative) | Coefficients |
|-----------|----------------------------------|--------------|
| Range 4   | -189.3442 °C to 0.01 °C          | A4 , B4      |
| Range 5   | -38.8344 °C to 0.01 °C           | A5 , B5      |

**Positive Range:** Accesses the coefficients to be used for temperatures above the triple point of water (0.01 °C).

| Recommend | ded Temperature Range (Positive) | Coefficients      |
|-----------|----------------------------------|-------------------|
| Range 6   | 0.01 °C to 961.78 °C             | A6 , B6 , C6 , D6 |
| Range 7   | 0.01 °C to 660.323 °C            | A7 , B7 , C7      |
| Range 8   | 0.01 °C to 419.527 °C            | A8 , B8           |
| Range 9   | 0.01 °C to 231.928 °C            | A9 , B9           |
| Range 10  | 0.01 °C to 156.5985 °C           | A10               |
| Range 11  | 0.01 °C to 29.7646 °C            | A11               |
| Range 5   | 0.01 °C to 29.7646 °C            | A5 , B5           |

#### A, B, C, D: ITS-90 coefficients

Note that the POSITIVE and NEGATIVE groups include a common range: **Range 5**. If you need to use their coefficients for the positive and negative ranges, set the coefficients equally for the positive and negative ranges. The coefficient values can be found in the reference sensor certificate.

After filling in the blanks, click the **SAVE** button and confirm. The new sensor is now available to be chosen from the list. To edit data from a sensor, select it and press the **EDIT** button. To remove a sensor, select it and press **REMOVE**.

**PROBE** refers to temperature measurement with an optional 4-wire Pt-100. Using the probe you can measure the temperature with high accuracy. There is also the option to configure the Callendar-Van Dusen or ITS-90 sensor coefficients, which follows the same procedure for the RTD input sensors as above.

For **TC** (thermocouple) input, you must select the thermocouple type and the type of cold junction compensation (CJC): **Internal, Manual** or **Probe**. In **Internal** option, the compensation is done internally; In **Manual** you must set the value of the temperature of the cold junction to the calibrator. The **Probe** option corresponds to measuring the cold junction through a probe sensor or the external cold junction compensation block of high accuracy. One can use this block to accurately measure the cold junction of both input and output thermocouple. Connection details can be found in item d) of this same section. You can also enter thermocouple curves as well as RTD curves. Select **CUSTOM** and choose one of the registered thermocouples from the list. To enter or edit data

from a sensor, press the edit button and save or change the parameters of the sensors.

**PRESSURE** option relates to pressure measurement with the MCS-XV through the optional pressure sensors. It should also select the pressure sensor to be read (C1, C2, C3 or C4). To use the optional BR - Barometric to indicate the pressure of any other sensor in Absolute mode, use Channel-2 (Enable channel-2 in the Quick Menu > CH-2). Select the sensor to use, click gear icon and select ABS. When the MPYA optional pressure module is connected to the MCS-XV's USB port, the **PRESSURE** option will also show the option of choosing the module as a pressure input.

The **SWITCH** input is a measurement of continuity of an external contact connected to the input (between RTD1 and RTD4) of MCS-XV. When there is continuity, the input shows **CLOSED**, otherwise it shows **OPEN**. By pre-selecting the pressure indication on channel-2, in **SWITCH** the automatic pressure test function is enabled. In this function it is possible to check the contact opening and closing values of pressure switches. This requires a pressure source that varies at a slower ramp for greater accuracy. For these tests, it is recommended to increase the read rate of the A/D to **FAST** converter. See more information in section **2.4.7** - A/D RATIO.

Select SWITCH then PRESSURE SWITCH TEST. The following screen is shown. Fill in the pressure switch identification fields and values for TRIP (value for closing/ opening of the pressure switch relay), DEAD ZONE

(pressure hysteresis value) and **TRIP ERROR / DEAD ZONE ERROR** (tolerance values for trip and zone error dead for PASS/FAIL of pressure switch). For test reporting, use the **TASKS** function.

| TAG          | 196330081                  | EST ANGUMETERS                | - /  |            |          |
|--------------|----------------------------|-------------------------------|--|------------|----------|
| STRIAL HUMBE |                            | 7690                          | 20,000   | 191422.008 | 1.000    |
| HODEC        | -1                         | DEADIONS                      | 20,600   | DEADIDHE   | 5.000    |
| 0.053 m      | si l                       | ta T                          | No Y   |            | Stav1    |
| 0.000 ps     | _                          |                               | 100  |            | Silver.  |
| 1            | PRESSURE<br>OPEN<br>25 pst | DEADZON<br>59,995 ps<br>CLOSE | ACT AT START   | psl        |          |
|              | PRESSURE<br>OPEN<br>25 pst | DEADZON                       | ACT AT START<br>NE 23.130<br>I<br>I<br>II<br>II<br>II<br>II<br>II<br>II<br>II<br>II<br>II<br>II<br>II<br>I | psl        | PASS/PAU |

Fig. 14 - Pressure Switch Automatic Test

When the input sensor breaking occur (RTD, resistance or probe) the display will show the burn-out warning identified by question marks illustrated below:



Fig. 15 - Burn-out Warning

Whenever the input signal is above or below the input ranges established in Section 1.2 - Specifications, the display indicates OVER or UNDER, respectively.

The units of temperature and pressure can be changed by clicking on the engineering unit (°C, °F, psi, atm etc.) and selecting the desired option.



Fig. 16 - Selecting the Engineering Unit

The **NONE** option turns off the input function.







Fig. 17 - Input Connections





#### c) Probe Connection (optional)

Connect the **PROBE** to MCS-XV so that polarity identifications match. See figure below.



#### d) High Accuracy External Cold Junction Compensation Block Connection – CJCB (optional)

Insert the high precision block in the TC input (IN) or TC output (OUT) terminals, and connect the cable which comes out of the block to calibrator Probe connector according to the same polarity described in item c) above. Depending on the block insertion in the TC input or in the TC output, the thermocouple connection will have its input or output cold junction given by the external compensation block. The input or output thermocouple connection must be made in the external compensation block itself. See the following figures:




Fig. 19 - CJCB Connection


For an effective input or output cold junction measurement with the block, the **PROBE** option of thermocouple cold junction must be selected and enabled. In **CJC TYPE** select **PROBE**.

## 2.4.2. Generation or Output Functions

## a) Output Type Configuration

Press the **OUTPUT** button, select through the menu the type of signal to be generated and use the corresponding terminals (see **Figure 22 - Output Connections** or press the **HELP** button).

| SIGNAL: V | OUTPUT S  |         |                | $\nearrow$ |
|-----------|-----------|---------|----------------|------------|
| v         | mV        | mA      | онм            |            |
| NONE      | FREQ.     | тс      | RTD            |            |
|           |           |         |                |            |
|           | SPECIAL P | ONCHORS | and the second |            |



The **FREQ.** option allows the selection of the frequency or pulse generation. For the frequency generation, it must be chosen between the bands of 100 Hz or 10000 Hz. It can also be adjusted the amplitude, which varies from 0 to 22 V. For the pulse generation (square wave) in addition to the amplitude and the number of pulses, one must provide the rate at which the pulses should be sent, given in Hz. The pulse sequence is sent as soon as OK is pressed.

For the **RTD** or **OHM** generation, the calibrator simulates electronically a resistance value, i.e., there is no resistor but an electronic circuit which behaves as a resistor. It was designed specifically with the purpose of simulating RTD so that the calibrator can be connected to instruments such as indicators, transmitters, temperature controllers, with an excitation current within the range of 150  $\mu$ A to 5 mA. For **OHM** generation, you should choose between the range of 400  $\Omega$  and 2,500  $\Omega$ .

For the thermocouple (**TC**) generation, you must choose the type of thermocouple and the type of cold junction compensation. For both RTD and TC outputs it is possible to configure correction curve coefficients (see item 2.4.1.a. to configure the curves).

To change the value of the output, press on the number and type the desired value on the keyboard.

Another way to change the output value is to modify each digit separately in fixed steps. To do this, hold the output value for at least 3 seconds, choose the digit to be changed (the selected digit is indicated with arrows  $\vee$  and  $\wedge$ ), and press the buttons  $\vee$  and  $\wedge$  to change the setpoint. To exit this edit mode, hold down the output value for at least 3 seconds.





Fig. 21 - Changing the Output Value


The temperature units can be changed by clicking on the unit and selecting the desired option. The **NONE** option disables the output function.

## b) Output or Generation Connections







тс



(Side connection) Use TC compensation wires



Note: For RM version, use standard thermocouple sockets as shown.







Note: For DT version, connect the TC wires into the terminal screws, according to the figure above.

# Fig. 22 - Output Connections





Fig. 22 - (Cont.) Output Connections

# 2.4.3. Available Power Supplies

The MCS-XV has two power supplies galvanically isolated: TPS and +22.5 Vdc at the output, both provided with short-circuit protection (current limited to 30 mA).



## 2.4.4. Input Special Functions

Selecting SPECIAL FUNCTIONS in the input channel, the display will show:

| SIGNAL: V    |              | NO SPECIA | L FUNCTION |
|--------------|--------------|-----------|------------|
| SPECIAL FUNC | CTIONS SETTI | NGS       | 8 2        |
| CONV         | SCALE        |           |            |
|              |              |           |            |
|              |              |           |            |
|              |              |           |            |
| INPUT CH-1   | SPECIAL FU   | NCTIONS   | HELP       |

Fig. 24 - Input Special Functions

The selected special function will act on the previously selected input.

After selecting and configuring the special function, to enable it change to on the key status on and confirm in **OK**. To disable it change the key to **OFF**. To change the state of the key, just click on it.

When there is no active special function, the screen displays the message NO SPECIAL FUNCTION at the

top.

### a) SCALE Function

It establishes a linear relationship between the MCS-XV input signal and what is shown at the display, according to the graphic below:




Fig. 25 - SCALE Function (LINEAR)


The scaled indication at the display (#) may be changed to represent any engineering unit, such as: m/s, m<sup>3</sup>/s, % etc.

The number of decimals, up to 4, shown at the display may be configured.

The value for **Input High** must be necessarily higher than **Input Low**. On the other hand, **Scale High** and **Scale Low** may have any relationship between themselves: higher than, lower than or equal to, and they may have a signal before them. Thus direct or reverse relationships may be established.

The counter and the contact inputs cannot be scaled.


For the current input, a linear relationship may be established as it has been previously shown or it may be squared **(FLOW)** as illustrated below:



#### b) CONV Function

By using the **CONV** function, the calibrator may convert any input signal into any output signal with galvanic isolation. It may, therefore, behave as a real transmitter.

Once the calibrator input and output have been selected, fill in the four parameters shown in the graphic below:



The value of **Output High** must always be higher than **Output Low**. **Input High** and **Input Low** parameters must never be equal. Thus any type of direct or reverse retransmission, from input to output, may be obtained.

# 2.4.5. Output Special Functions

Selecting SPECIAL FUNCTIONS in the output channel, the display will show:

|        | ÷       |           |      |
|--------|---------|-----------|------|
| SCALE  | RAMP    | STEP      |      |
|        |         |           |      |
| ουτροτ | SPECIAL | FUNCTIONS | HELP |

Fig. 28 - Output Special Functions

The selected special function will act on the previously selected output.

After selecting and configuring the special function, to enable it change to on the key status on and confirm in **OK**. To disable it change the key to OFF. To change the state of the key, just click on it.

When there is no active special function, the screen displays the message NO SPECIAL FUNCTION at the

top.

#### a) RAMP Function

By using this programming, the MCS-XV output varies automatically, producing ramps and level marks which may be programmed to actuate once or continuously.

It must be entered the start and the end values of the range within which the output will vary (**MIN** and **MAX**), and the **TIME** value (in seconds) required for a complete ramp within the range. Another value that may be configured is how long it should dwell at the level mark (**WAIT**), i.e., the time during which the output remains constant between two ramps. After setting up the special function and activate it (change the key  $\bigcirc$  in special function) and press OK. To start the ramp press the chronometer icon  $\bigcirc$ . The ramp runs continuously in accordance with the defined strategy ( $\uparrow \downarrow \uparrow \downarrow$ ). To stop the ramp, press  $\bigcirc$ .

## b) STEP Programming

The **STEP** programming makes the calibrator output vary in pre-defined steps. It is useful in calibrations where some scale points are verified; for example 0% - 25% - 50% - 75% - 100%.

To generate setpoints, you must set the minimum and maximum range points (MIN and MAX), the output percentage change for each step (%), and generate the list ( button).

There is also the option to manually add or delete any point to the list of setpoint values ( button: adds a point to the list, local button deletes the selected point, button deletes all points).


If you want each step is achieved automatically after a preset time, you must set the **TIME** in seconds. In this situation the steps are generated automatically and continuously. Activating the function and pressing **OK**, the output starts executing the **STEP** program, always starting from the beginning of the range. To move to the next step you must press  $\uparrow$ . Pressing  $\checkmark$  it goes to the previous step. Pressing  $\bigotimes$ , the steps are automatically and continuously generated according to the set time. To stop, press

#### c) SCALE Function

The scaling of the output from MCS-XV allows it to simulate the operation of a transmitter. In this case, the display scaled indication (#) simulates the transmitter input (which can be changed by pressing the number indicated on the display and entering the desired value), and as output signal it can have any of the signals generated by the MCS-XV (e.g. 4 to 20 mA).

SCALE output function relates the output signal generated by the MCS-XV with what is shown on the display as the example shown below.

The scaled indication at the display (#) may be changed to represent any engineering unit, such as: m/s, m<sup>3</sup>/s, % etc.




The number of decimals, up to 4, shown at the display may be configured.

The value for **Input High** must be necessarily higher than **Input Low**. On the other hand, **Scale High** and **Scale Low** may have any relationship between themselves, as long as they are not equal. Thus direct or reverse relationships may be established.

Any type of output can be scaled, except the pulse output.

For the current output, a linear relationship may be established as it has been previously shown or it may be squared (FLOW) as illustrated below:



# 2.4.6. Saving Current Configuration (Memory Manager)

The MCS-XV multicalibrator admits several special functions that may become of frequent use. In these situations, it is useful to store such settings in the instrument in order to save time.

After setting the desired calibration mode (input type, output type or special functions), press the icon **Source NORE OPTIONS**, and the button **MEMORY MANAGER**. On the bottom of the screen, type a name for this configuration and a description. Press the **SAVE** button.

The operation that was being performed by the MCS-XV shall be stored in memory identified by the name given to it. To use it again, even after the MCS-XV is turned off and on, select the name of the desired setting and press the **LOAD** button. The **SAVE AS DEFAULT** button sets the current configuration as the default configuration of the calibrator. Thus, every time the MCS-XV is turned on, this will be the initial configuration of the calibrator.

## 2.4.7. AD/Ratio

The MCS-XV multicalibrator allows you to change the conversion rate of the Analog/ Digital Converter. At faster rates, the readings indicated in measure mode update more often, and at slower rates the calibrator takes more readings and updates the values at a lower frequency.

For tests where read speed is important, such as Pressure Switches testing, it is recommended to use a faster rate that can "capture" the nearest relay open / close value. For calibrations and other tests, it is recommended to use a slower conversion rate, which provides more accurate readings.

To change the conversion rate, press the icon **Solution** > MORE OPTIONS, and the AD/ RATIO button. Select between FAST, MEDIUM and SLOW and confirm in OK.

## 2.4.8. Bar Graph

The MCS-XV multicalibrator allows you to monitor an input and include HIGH and LOW alarms for the range.

To set the alarm, press the icon S > MORE OPTIONS, and the BARGRAPH button. Select between HIGH and / or LOW alarms. Press BEEP to have the calibrator beep when in alarm. In EVENTS it is possible to check a list of the time when the alarm detected values outside the registered tolerance.

Pressing the icon ki it returns to the Calibrator menu, keeping the monitoring bar next to it.

Pressing the icon , a screen for stability / leak testing is presented. Select the time in seconds and click **START** to run the test. Choose which unit to display results in engineering unit per seconds (S), minutes (M) or hours (H).

#### 2.4.9. Calibration Examples

#### a) Calibration of a Temperature Transmitter (RTD Input and 4-20 mA Output)

Through the menus, you can configure the MCS-XV for mA input and output in RTD. The TPS, which means Transmitter Power Supply, is a source of 24 Vdc that provides power to the transmitter.

In the example, the connection of the RTD is made using three wires and being simulated by the MCS-XV. With this form of connection, there is no measurement error due to the resistance of the wires, since these have the same length and gauge.




Fig. 31 - Calibration of a Temperature Transmitter 3-wire RTD Input

# b) Calibration of a 4-wire Temperature Transmitter (110/220 Vac Power Supply - Thermocouple Input and 1-5 Vdc Output)

Setup the MCS-XV as volts output and TC input, and select the **TC** type. For the cold junction compensation, you can use compensating wires TC to connect the transmitter to the MCS-XV and choose the option of **Internal** cold junction compensation, or you can measure the temperature of the terminal of the transmitter and enter this value in the **Manual** option in the MCS-XV, thus eliminating the use of compensating wires.





Fig. 32 - Calibration of a Temperature Transmitter (Thermocouple Input and 1-5 Vdc Output)

#### c) Pressure Transmitter Calibration

Use **TPS** MCS-XV source to power the two-wire transmitter 24 Vdc and connect the current as illustrated below. Select **mA** (current) in the Input menu of the CH-1 and **Pressure** Input on CH-2 menu. To enable channel 2 as input, press the icon and enable the CH-2 option. To return to the Calibrator screen press the **BACK** button.




Readings of mA input can be scaled to pressure through the **SCALE** option (see item **2.4.4.a**). Thus the error between the input and the output of the pressure transmitter is easily calculated.

#### d) Pressure Switch Verification

Pressure switches are devices that receive a pressure signal and have relay alarm. The relay is activated whenever the pressure passes above or below a certain setpoint alarm.

Connect the pressure switch output to the switch input of MCS-XV, **RTD1** and **RTD4** terminals, and make the pneumatic connections as illustrated in the figure below:



Channel 2 must be enabled and selected **PRESSURE**. You must select the corresponding sensor. On channel 1, select **SWITCH** input and enter **PRESSURE SWITCH TEST**.

The MCS-XV shows the pressure measurement and the contact status (open or closed).

Press **RUN** to start the test after filling in all required fields.

Vary the pressure manually or with the help of an automatic pressure controller. The instant the relay changes position, it is shown on the display the alarm setpoint pressure switch, so the change from open to closed or from closed to open.

### 2.5. HART<sup>®</sup>


The MCS-XV can be used to read and set parameters in devices that have HART<sup>®</sup> Communication Protocol. The HART<sup>®</sup> Protocol allows digital communication between master (in this case, the MCS-XV) and the slave (field instrument) superimposed on the 4-20 mA analog signal. To access this function from the main menu, select the **HART<sup>®</sup>** option.

The calibrator has two versions: CH (HART<sup>®</sup> Calibrator) and FH (Full-HART<sup>®</sup> configurator with DD library).

The **CH** option has basic and universal commands for HART<sup>®</sup> communication (zero, span, trim mA etc.) that allow you to adjust the range of the instrument, monitoring the primary variable, current adjustment etc. The **FH** option, in addition to basic and universal commands, is provided with the DD library (Device Description) from *FieldComm Group* and allows the setting of specific parameters of each instrument.

# 2.5.1. HART<sup>®</sup> Connections

When selecting HART® from the main menu the **mA INPUT + HART** and **ONLY HART (INCLUDING NETWORK)** options are shown. Can also be enabled or not the internal resistor (250  $\Omega$ ). The option must be chosen according to the type of connection to be made.







Fig. 36 - Transmitter Powered by an External Power Supply mA INPUT + HART<sup>®</sup> (Internal Resistor Enabled)

To the connections shown in Figure 35 and Figure 36, use the mA INPUT + HART® option and INTERNAL RESISTOR enabled. In this mode, the 250  $\Omega$  resistor is activated internally in series with the calibrator mA input. The calibrator can measure current from the transmitter and also read and set parameters via HART®. If the internal resistor is not enabled, an external resistor of at least 150  $\Omega$  must be inserted in series with the mA input. To power the transmitter, can be used the TPS MCS-XV source (Figure 35) or an external source (Figure 36).



60

**IMPORTANT:** Before connecting the calibrator to the transmitter as shown above, ensure that the mA Input is not selected in the MCS-XV (enter in the Calibrator menu, and select any CH-1 Input other than mA or none).

For the connection shown in **Figure 37**, use the option **ONLY HART**<sup>®</sup>. In this mode, the internal resistor and the mA input are disabled. The HART<sup>®</sup> resistor (at least 250  $\Omega$ ) must be externally inserted in series with the power source and the transmitter. In this case, the calibrator does not perform the measurement of the transmitter current, but can read and configure its parameters via HART<sup>®</sup>.

## 2.5.2. Starting Communication

Entering the **HART**<sup>®</sup> menu, the following screen is shown. Enabling the **HART**<sup>®</sup> **CONFIGURATOR** option (only for **FH** version), you have access to the Full-Hart software (DD library) with all device parameters. Disabling this option, the **CH** software is launched with basic and universal commands for HART<sup>®</sup> communication (zero, span, trim mA etc.).




Fig. 38 - Choosing between CH or FH option

Then, define the Internal Resistor (250  $\Omega$ ) and the configuration of HART<sup>®</sup> connection type (mA input + HART<sup>®</sup> or ONLY HART<sup>®</sup>).

For the CH option, insert the ADDRESS of the HART® device and press the CONNECT button. If the

instrument address is unknown, can be used the **SEARCH** button, which will search the device in the address range from 0 to 15. For the **FH** option, the device is automatically found.

Up to 15 devices on a HART network (addresses 1-15) are allowed. In connection with a single field instrument with poll address 0 and **mA INPUT + HART** (B) connection, the primary variable can be read either in analog (4-20 mA) and digital form (HART<sup>(B)</sup>). In networking, the only way to read the primary variable is digitally (**ONLY HART**<sup>(B)</sup>).

# 2.5.3. Adjusting the Measurement Range of a HART<sup>®</sup> Transmitter (CH Option)

When connecting, appears in the **DESCRIPTION** tab data identifying the instrument, such as TAG, manufacturer, description, message, date, measuring range and input filter (damping). Some of these parameters can be changed in the **DEFAULT SETTINGS**.

In **DESCRIPTION** tab, the **MIN** and **MAX** fields indicate the measuring range of the HART<sup>®</sup> transmitter. For PV (primary variable) equal to the MIN value, the transmitter should generate 4 mA. For PV (primary variable) equal to MAX value, the transmitter should generate 20 mA. The maximum allowable range of the transmitter is shown just above (**RANGE** ...). To edit the range of the transmitter, just change the MIN and MAX values and press the **SAVE RANGE** button.

On this screen you can also edit the unit of the primary variable and the input filter (damping).

|                    |                 |      |      |   | _    |
|--------------------|-----------------|------|------|---|------|
| MANUFACTURER       | Presys          |      |      |   |      |
| REVIEW             | 5               |      |      |   |      |
| TAG                | TT-01           |      |      |   |      |
| DATE               | 08/08/2018      |      |      |   |      |
| MESSAGE            |                 |      |      |   |      |
| DESCRIPTOR         |                 |      |      |   |      |
| tange: -200 850 °C | -               |      |      | _ |      |
| MIN 0              | Transmitter mea | UNIT |      | • | SAVE |
|                    | SAVE RANGE      |      | 1000 |   |      |

Fig. 39 - Adjusting the measuring range of the HART® transmitter

# 2.5.4. Adjusting the Measurement Range of a HART® Transmitter with Reference (CH Option)

The range of the transmitter can also be adjusted generating the minimum and maximum values of the desired range in the transmitter input and adjusting these values as minimum and maximum (set by reference). Select Input mA and press the HART<sup>®</sup> button. Connect the transmitter to the mA input. The reference value inserted in the transmitter input can be generated or measured by the MCS-XV itself. For this, before connecting the HART instrument, from the main menu, select CALIBRATOR, and select on Channel 2 the type of desired signal.

For instance, to adjust the range of a Pt-100 temperature transmitter, select in **CALIBRATOR** menu **RTD Pt-100** as output and connect it to the transmitter input. For a pressure transmitter, channel 2 must be set as **PRESSURE** input and the pressure must be generated manually with a pump, e.g., and connected to the MCS-XV.

To enable channel 2 as input, press the icon and enable the **CH-2** option. To enable channel 2 as output disable **CH-2** option. To return to the calibrator screen press the **BACK** button. The signal measurement or generation of **CH-2** will work as the standard value for the adjustment range of the instrument.



Fig. 40 - Quick Hart® Adjustment with Reference

Generate the signal to the transmitter input corresponding to the lower range value and press the button. Transmitter will generate 4 mA to this value. Generate the signal to the transmitter input corresponding to the upper range value and press button. Transmitter will generate 20 mA for this value.

Another way of doing the range adjustment by reference is entering in the HART option. Back to the main menu by pressing the icon and the HOME button. Select HART<sup>®</sup>, set the connection type, address and then press CONNECT.

For this setting, select the **MONITORING** tab. In this screen are shown the value of the primary variable (PV) read by HART<sup>®</sup> (digital), the current that the transmitter wants to generate (**AO** - **DIGITAL OUTPUT**), and the current measured by the MCS-XV (**ANALOG READ**).

To adjust the range of the transmitter, generate the signal to the transmitter input corresponding to the lower range value and press the  $\downarrow$  **Inf Range** button. Transmitter will generate 4 mA to this value. Generate the signal to the transmitter input corresponding to the upper range value and press  $\uparrow$  **Sup. Range.** Transmitter will generate 20 mA for this value.

| PRIMARY VARIA                                  | BLE 0.00 °C  | mais   |
|--|--|--|
| DIGITAL OUT                                    | <sup>рит</sup> 4.00 mA   | •  |
| ANALOG RE                                      | ead 4.00 mA  |  |
| SUP. RANGE Adju                                | ustment of the<br>ssurement range                              |  |
| INF. RANGE with                                | ustment of the<br>ssurement range<br>or reference OUTPUT: 0.00 | and the second |
| SUP. RANGE Adju<br>INF. RANGE with<br>SET ZERO | ustment of the<br>surgement range<br>or reference OUTPUT: 0.00 | °C<br>Calibrator Chan  |

Fig. 41 - Adjusting the Measuring Range of the HART® Transmitter with Reference

In **MONITORING** screen, beyond stating the primary variable PV and the transmitter current, is shown the measured or generated value by the MCS-XV in **CH-2**. If the **CH-2** is configured as an output, click on the number to change the value of output.

# 2.5.5. Checking / Adjusting HART<sup>®</sup> Transmitter mA Output (CH Option)

In **DEFAULT SETTINGS** tab can be adjusted the output current of the HART<sup>®</sup> transmitter (output trim) according to current measured by MCS-XV. You can make this adjustment only when the MCS-XV is connected to a single transmitter with address 0, in the **mA INPUT + HART<sup>®</sup>** option of connection, since the calibrator needs to measure the current to make the adjustment.

Before performing the adjustment, a transmitter output current check can be performed by pressing the **CHECK** button. The transmitter will generate fixed current (4, 8, 12, 16, 20 mA) and the calibrator will show the measured values for each point.

To adjust automatically, simply press the **AUTO** button. The calibrator will send the command to the transmitter to generate 4 and 20 mA (fix), make the measurement of these points, and adjust the output (trim). The adjustment is completed when **D/A Adjustment Completed** message appears.

The **LEAD TIME** field sets the time (in seconds) of each point stabilization time.

|   | N  |          | TAG AND MESSAGE DEFINITION           |   |        |
|---|--|----------|--------------------------------------|---|--------|
| MESSAGE TRANSM R                            | та   | SAVE MSG | MESSAGE TRANSM RTA                   |   | SAVE M |
| TAG: 1235<br>DESCRIPTOR                     |  | SET TAG  | TAG: 1235<br>DESCRIPTOR TESTE PRESYO |   | SET T/ |
| SETTLING TIME 5<br>D/A AUTO TRIM<br>CHECK 2 | MODE 4mA FIX_<br>VALUE 3.9973 SAVED<br>MODE 2000A FIX_<br>VALUE 20.0055 SAVED<br>D/A ADJUSTMENT COMLPETED. |          | D/A AUTO TRIM<br>CHECK               | MODE 4.000mA, FIX_<br>READ: 3.998 mÅ<br>MODE 8.000mA FIX_<br>READ: 8.001 mÅ<br>MODE 12.000mA FIX_<br>READ: 12.004 mÅ<br>MODE 16.000mA FIX_<br>READ: 16.003 mÅ<br>MODE 20.000mA FIX_ |        |

Fig. 42 - Checking / Adjusting the mA HART® Transmitter Output


# 2.5.6. Full-Hart Configurator (FH Option)

If the **HART CONFIGURATOR** option is enabled the **FH** Software is launched. For this option, the device is automatically found and the screen shows the basic, universal and specific parameters (DD library).

To start the HART configurator you should wait the MCS-XV to read the device parameters. The MCS-XV will show the message *Reading device information. Please wait...* After connecting, at the bottom of the screen it shows the TAG, connected instrument model and the DD file (Device Description) used.

You can open the instrument configuration tree, located on the left side of the screen. This configuration tree changes according to the instrument, as each HART<sup>®</sup> transmitter has its specific commands.

| Device View Help ?  | 10 🖉 👔                 | 20             |       |
|---------------------|------------------------|----------------|-------|
| - P Online          | Item                   | Value          | Units |
| Device setup        | A Manufacturer         | PR etectronic  | 1     |
| Process variable:   | Model                  | PR 5335        |       |
| Diag/Service        | Tag                    | To1            |       |
| G Status            | A Descriptor           | TRANSM TEM     |       |
| Calibration         | No Message             | TECNICA PRE.   |       |
| Write protecti      | A Date                 | 05/05/2015     |       |
| Basic setup         | Write protect          | Not write prot |       |
|                     | Snsrs/n                | 9              | 6 4   |
| 🖶 🚘 Detailed setup  | S Final asmbly num     | 0              |       |
| Review              | 2 Distributor          | PR Electronic  |       |
| 🗀 Input info        | A Hardware rev         | 23             | 6     |
| Output Info         | Software rev           | 34             |       |
| Device inform       | 🗠 Universal rev        | 5              | 5     |
|                     | S Fld dev nev          | 1              |       |
|                     | Sensor errors          | 0000           |       |
|                     | ADC errors             | 0x00           |       |
|                     | Misc. errors           | 0x00           |       |
|                     | SOEM date 0            | Öxff           |       |
|                     | OEM data 1             | Oxff           |       |
|                     | OEM data 2             | Oxff           |       |
| Tag: 101 Device: PR | 5335 - DD: 6d/ef/01/01 | HAD            | T Msg |



Double-click the parameter you want to change and edit the desired value.

Parameters identified with the icon have methods. To change them, just double-click the parameter and follow the steps shown.

For other parameters, after editing the value the field becomes yellow, indicating that it has been changed,

but not saved in the transmitter yet. To confirm click on the button 🔁. To cancel, press 🥙

To view the MCS-XV mA input value or change the output setpoint, press the 💻 button:




Fig. 44 - MCS-XV Input and Output Values

To view the device status, press the VIEW menu and DEVICE CONDITION:




Fig. 45 - Device Condition

To save all the configuration of a HART<sup>®</sup> instrument connected to the MCS-XV, can be used the **Document Device** function, from the **Device** menu. This function is useful to save the configuration of an instrument for later download to another instrument of the same model, or else just to make a backup of the settings made.

Press **Device**  $\rightarrow$  **Document Device**, fill in the **File Name** blank and press **Save Device Config**. Optionally, it can be given a description of the configuration file in the **Notes** blank.

| Device View Hel | p 🕅 🦉 🕈  | 26  |                    |
|-----------------|--|-----|--------------------|
| 2 Online        | Item   | Val | ue Units           |
|                 | Device setup<br>PV<br>Device setup<br>PV<br>Device setup |     | oo degC<br>85 degC |
| ocument Device  |  |     | ×                  |
| Flations        |  |     |                    |
| Thi - laszer    | t  |     |                    |
| Falter          |  |     |                    |
|                 |  | 11  |                    |
|                 |  | 14  | i i                |
|                 | SeverDandeCortg  |     |                    |
|                 |  |     |                    |
|                 |  |     |                    |

Fig. 46 - Saving a Device Configuration

When you want to download a saved configuration for an instrument, access the menu  $Device \rightarrow Download / View$ . To select the desired configuration file, double-click it.

Press the **Write** button to download the configuration file for the connected instrument. Before the instrument is fully configured, some confirmation messages will be displayed. To cancel, press **X**. To proceed, press **OK**. At the end of configuration, the **Configuration Write Complete** message appears.

# 2.6. Data Logger

72

The MCS-XV allows you to record series of measurements over time to display data in chart or table format. Select **CALIBRATOR** from the main menu and select the desired type of signal on channel 1 and channel 2. Press the icon and select **DATA LOGGER.** The calibrator automatically starts the measurements and displays each measured point on the chart.

For measurements to be saved, you must press the **REC** button (see **Figure 47**). With this option selected, all points (measurement and time) are saved in an internal file in MCS-XV, which can be used to generate a table or chart.




Fig. 47 - Data Logger




Fig. 48 - Data-Logger Configuration Menu

Entering in the Configuration Menu, in **CONFIG** option, you can edit the background color of the chart, color and line thickness, sampling rate (in seconds) and set the x (time) and y (measurements) axis of the chart.

Recording can also be programmed to start at a certain date and time in the LOGGER option. Just set the start time and end time of recording. During the defined range, the measured points are saved in an internal file in MCS-XV.

To view a saved file press the **OPEN** button, select the desired file, and press **LOAD**. The file name contains the date and time of the measurements.

The **SHEET** button allows the visualization of data in table format, with the date and time of the measurement and the measured values.

If the user wants to export the current data to a .csv file that can be opened in spreadsheet softwares, press the **SAVE** button and indicate the name and where it will be saved. The button saves the current screen image as a .png file. All saved screens can be viewed in the **IMAGE** menu. These files are saved in the internal SD card of the calibrator. If a USB Pen Drive is connected to MCS-XV, you can choose between saving in the internal SD card or the Pen Drive.

To access the files saved in the internal SD card of the calibrator, connect the USB cable to the computer (type A USB) and to the MCS-XV (Type B USB - Device, see **Figures 02, 04 and 05**, portable, RM and DT versions, respectively).

# 2.7. Automatic Tasks

In MCS-XV, can be created and performed automatic calibration tasks. This option can be used to generate calibration work orders of transmitters and indicators.

# 2.7.1. Creating Tasks

To create tasks from the main menu, select **CALIBRATOR**. Select the desired type of signal on channel 1 and channel 2. For example, to calibrate a thermocouple temperature transmitter, select TC output (which will be connected to the transmitter input) and mA input (which will be connected to the current output of the transmitter). For a voltage indicator, e.g., selected output V (which is connected to the indicator input) and NONE for the input (the instrument reading will be inserted manually).

# Press the $\blacksquare$ icon, and select **TASKS** $\rightarrow$ **CREATE NEW TASK**.

Fill at least the serial number of the instrument to be calibrated, instrument TAG, stabilization time for each point (waiting time in seconds) and the maximum error allowed for the instrument to be calibrated (in % of the span, reading or full scale). By filling the stabilization time with the value 0 (zero), the calibrator requests to the operator to manually confirm point acquisition.

|              |                                       |                 |          |            |          |      | 8 |
|--------------|---------------------------------------|-----------------|----------|------------|----------|------|---|
|              |                                       | OPEN T          | EMPLATE  |            |          |      |   |
| CREATED BY   | John A                                |                 |          |            | 0        | 0    |   |
| MANUFACTURER | Presys                                |                 |          |            | Θ        | 0    |   |
| MODEL        | RTD Transi                            | RTD Transmitter |          |            |          | 0    |   |
| MESSAGE      | Connect the transmitter to the MCS-XV |                 |          |            | Θ        | 0    |   |
| AREA         | LAB                                   |                 |          |            | 0        | 0    |   |
| CUSTOMER     | Presys Inst                           | rumentos        |          |            | 0        |      |   |
| PROCEDURE    | CP-01                                 |                 |          |            | Ø        |      |   |
| SERIAL NO.   | 001.01.15                             | d               | 0        | SETTLING T |          | 10   | 1 |
| TAG          | TT01                                  | 6               | 0        | MAX ERR    | OR (%)   | 0.1  |   |
| ERROR SOURCE | SPAN                                  | -               | 0        |            |          |      |   |
| Task info    |                                       | AsFoun          | d/AsLeft | Re         | view and | Save |   |

Fig. 49 - Task Information


Go to the **As Found/ As Left** tab. Add each point to be generated by the MCS-XV and the expected value for the instrument under calibration both **As found** (calibration done before adjustment) and **As left** (calibration done after adjustment) values. Points can also be generated with the help of **AUTO** button. By pressing this button, simply enter the maximum and minimum values of the calibration range and the amount of points that it will be generate a list of points considering the same steps and a linear scale. Also fill the number of repetitions (**REP**) of the readings, and the calibration strategy (initial to the final point  $\uparrow$ , final to the initial point  $\downarrow$ , etc.). The **REP** field in the **As found** calibration can be filled with the value 0 (the task will contain only **As left** calibration). The minimum value for the **REP** field in the **As left** calibration is 1.

| EXPECTED | 4.0000 0              | mA (IN)                 | 0.00 4.0000                                    |     |
|----------|-----------------------|-------------------------|--|-----|
|          | and the second second | And Street and          | 25.00 8.0000                                   |     |
| POINT    | 0.00                  | C (OUT)                 | 50.00 12.0000                                  | 3   |
| REP      | 10                    | AUTO                    | 75.00 16.0000                                  | 1.0 |
| iner:    |                       |                         | 100.00 20.0000                                 | 10  |
|          |                       |                         |  |     |
|          |                       |                         |  |     |
| FT       |                       |                         |  | ~   |
| EXPECTED | 4.0000 (              | 3 mA (IN)               | 0.00 4.0000                                    |     |
| EXPECTED | -                     | - 77                    | 25.00 8.0000                                   |     |
| -        | -                     | 3 mA (IN)<br>3 °C (OUT) | 25.00 8.0000<br>50.00 12.0000                  |     |
| EXPECTED | -                     | - 77                    | 25.00 8.0000<br>50.00 12.0000<br>75.00 15.0000 |     |
| EXPECTED | -                     | o ra coum               | 25.00 8.0000<br>50.00 12.0000                  |     |

Fig. 50 - Task Points and Strategy

Go to the **Review and Save** bar. Choose an identification name/number for your task. If you want to save the model of this task for later use in creating other tasks, press **SAVE TEMPLATE** and give a name for it. When you want to open this model again, open the task creation screen and press **OPEN TEMPLATE** in **Task info** tab. Click on **CREATE** button to create it. The task is now saved in the calibrator.


| PROCEDURE:CP-01<br>INSTRUMENT DETAILS:  | rumentos<br>Costa Ramos, 260 - Saúde - Sã | io Paulo - SP |
|---|---|---------------|
| TAG: TT01<br>SERIAL NUMBER: 001.0<br>MODEL: RTD Transmitte<br>MANUFACTURER: Press<br>INPUT RANGE: 0 to 100<br>OUTPUT RANGE: 4 to 20 | er<br>ys<br>'C (RTD)                      |               |
| IDENTIFICATION  |   |               |
|   |   |               |
| W0-001  |   |               |
| WO-001<br>SAVE TEMPLATE   |   | CREATE        |




### 2.7.2. Performing Tasks

77

To perform a task created from the main menu select **TASKS**  $\rightarrow$  **EXPLORE TASKS**. A list identifying the created work orders that have not been performed yet (• **WAITING**) is shown. Select the desired task and press **OK**. Make the necessary connections between the calibrator and the instrument to be calibrated and press **START**.





The MCS-XV automatically starts to do the calibration generating setpoints registered on task and doing the reading of the instrument to be calibrated. If it was selected the **NONE** input, for each generated point the calibrator requires the value read by the instrument. The result will be displayed on the screen, and a progress bar is displayed to indicate the calibration remaining time. At the end of the calibration, a report is shown with the generated values, the obtained values, the expected values, and the error. If the error is higher than the registered value for the task, the line appears in red.

The first time that a task is performed, it will be saved as **As found** (before adjustment). If it runs again, it will be saved as **As left** (after adjustment). The results are saved in the calibrator and can be viewed at any time.

# 2.7.3. Viewing Results

Once a task has been performed, it remains saved in the calibrator.

To view the results of a calibration in MCS-XV, in the main menu select TASKS.

Enable the option • **PERFORMED**. The list will show only the tasks that have been performed. Select the desired work order and press **OK**. On screen, the report with the calibration points, the obtained values, expected values and the errors will be shown. If the error is higher than the value registered for the task, the line appears in red.

|           |            |              | PDF          | 8         |           | CREATE D   | OC VIEW     | PDF            | 0         |
|-----------|------------|--------------|--------------|-----------|-----------|------------|-------------|----------------|-----------|
| POINT     | EXPECTED   | OBTAINED     | ABS. ERR.    | SPAN ERR. | POINT     | EXPECTED   | OBTAINED    | ABS. ERR.      | SPAN ERR. |
| 0.00 °C   | 4.0000 mA  | 3.7751 mA    | -0.2249 mA   | -1.406%   | 0.00 °C   | 4.0000 mA  | 4.0002 mA   | 0.0002 mA      | 0.001%    |
| 25.00 °C  | 8.0000 mA  | 7.7942 mA    | -0.2058 mA   | -1.286%   | 25.00 °C  | 8.0000 mA  | 7.9978 mA   | -0.0022 mA     | -0.014%   |
| 50.00 °C  | 12.0000 mA | 11.8146 mA   | -0.1854 mA   | -1.159%   | 50.00 °C  | 12.0000 mA | 11.9971 mA  | -0.0029 mA     | -0.018%   |
| 75.00 °C  | 16.0000 mA | 15.8392 mA   | -0.1608 mA   | -1.005%   | 75.00 °C  | 16.0000 mA | 15.9995 mA  | -0.0005 mA     | -0.003%   |
| 100.00 °C | 20.0000 mA | 19.8605 mA   | -0.1395 mA   | -0.872%   | 100.00 °C | 20.0000 mA | 20.0004 mA  | 0.0004 mA      | 0.003%    |
|           |            |              |              |           | 100.00 °C | 20.0000 mA | 20.0003 mA  | 0.0003 mA      | 0.002%    |
|           |            |              |              |           | 75.00 °C  | 16.0000 mA | 15.9999 mA  | -0.0001 mA     | -0.001%   |
|           |            |              |              |           | 50.00 °C  | 12.0000 mA | 11.9977 mA  | -0.0023 mA     | -0.014%   |
|           |            |              |              |           | 25.00 °C  | 8.0000 mA  | 7.9979 mA   | -0.0021 mA     | -0.013%   |
|           |            |              |              |           | 0.00 °C   | 4.0000 mA  | 4.0007 mA   | 0.0007 mA      | 0.004%    |
|           |            |              |              |           |           |            |             |                |           |
| AS-FOUND  | AS-LEFT    | AS-FOUND ERR | AS-LEFT ERR. | DETAILS   | AS-FOUND  | AS-LEFT    | AS-FOUND ER | R. AS-LEFT ERF | . DETAILS |

Fig. 53 - Task Results

CREATE DOCUMENT option saves the job data as a PDF extension file to the calibrator's internal memory

(SD card), which can be printed or accessed via a computer. To print the Calibration Report, press the icon The printer must have been previously configured in SETTINGS > SYSTEM > PRINTER CONFIG (see section 3.4 and connected to the MCS-XV USB Host port (see Figures 02, 04 and 05, portable, RM and DT versions, respectively).

To access the files saved in the internal SD card of the calibrator, connect the USB cable to the computer (type A USB) and to the MCS-XV (Type B USB - Device, see **Figures 02, 04 and 05**, portable, RM and DT versions, respectively). Tasks are saved within the TASKS\REPORTS folder, identified by the registered TAG number.

To save all tasks to a connected USB flash drive or external HD, go to TASKS> ADVANCED TASK OPTIONS> EXPORT RESULTS TO PEN-DRIVE.

The logo can be changed to one of your own company. To do so, plug a PENDRIVE with the logo file into the MCS-XV's USB port. Enter the TASKS> ADVANCED TASK OPTIONS> ADVANCED> CERTIFICATE MODEL MANAGER> LOGO and select the file by its name (must have the extension .jpg). We recommend an image size of approx. 200 x 200 pixels.

To add your sign to the Report, create a user with a signature in System Menu (See section 3.4 - System) and enable the Protected Access with password.

In **ADVANCED TASK OPTIONS** you can configure / register the customers in **CUSTOMER MANAGER** which is ideal for calibration service providers;

| CLENTE-Proposition       TAGE TED     MODEL: HID Transmitter       TAGE TED     MAXEFACTURETRE Program       OUTPET RANCE to 2010A     MAXEFACTURETRE Program       DUTPET RANCE     MAXEFACTURETRE Program       TANDARDE     MAXEFACTURETRE Program   | SELAI                    | PI   | REPORT FOI<br>0-001    | IBRATION W     | CAI                         |                       |
|---|--------------------------|--|------------------------|----------------|-----------------------------|-----------------------|
| SERIAL NUMBERSH 01 15         MANUFACTURER (http:///intel.phspi.)           DUTPUT RANGE to 21 mA         MANUFACTURER (http://intel.phspi.)           DUTPUT RANGE to 21 mA         MANUFACTURER (http://intel.phspi.)           DUTPUT RANGE to 21 mA         MANUFACTURER (http://intel.phspi.)           MANUFACTURER (http://intel.phspi.)         MANUFACTURER (http://intel.phspi.)           MANUFACTURER (http://intel.phspi.)         MODEL (http://intel.phspi.)           MANUFACTURER (http://intel.phspi.)         MANUFACTURER (http://intel.phspi.)           MANUFACTURER (http  |                          |  |                        |                | mnentos                     | CLIENTE Pressys Instr |
| DUTPUT RANGE to 20 mA         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           IVET RANGE<br>(to the first (STR))         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)           MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)         MAX ERROR = 0.1%, SPAN (SPAN = 16 mA)  |                          | aroimikter .   | MODEL: RID I           |                |                             | TAG: TT01             |
| OLTPET RANGE 10: 21 (0.4)         MAX DEBOR - 0.3"S SPAN SPAN - 16 0.4.1           TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10: 10 (0.11)           Status 10: 10 (0.11)         TAYE TRANGE 10:   |                          | R: Presys  | MANUFACTURE            |                | 01.01.15                    | SERIAL NUMBER:0       |
| INTERANCE:           STANAAD:  | - 16 m 5 1               |  |                        |                | 701 on 6                    | OUTPUT RANCES         |
| Diff         Diff <thdiff< th="">         Diff         Diff         <thd< td=""><td>- to meet</td><td>a a stand stan</td><td>MAA CRROK-4</td><td></td><td>20.00%</td><td></td></thd<></thdiff<>  | - to meet                | a a stand stan   | MAA CRROK-4            |                | 20.00%                      |                       |
| MAXE PRESS         STRALL SUBJER         MODEL         NAST C-LL         CLER, NUMBER           PRESS         31.06.18         MCDEX         121/021         B999.8.05           Ar-Read primed by Jobs         DOT         SAFLT C-LL         CLER, NUMBER           POLY         SAFLT C-LL         DER, NUMBER         B071.12           POLY         SAFLT C-LL         DER, NUMBER         B071.12           POLY         SAFLT C-LL         DER, NUMBER         B071.12           POLY         SAFLT C-LL         DER, NUMBER         DER, NUMBER           POLY         SAFLT C-LL         DER, NUMBER   |                          |  |                        | _              |                             |                       |
| As-king preference by John         DATE 127 (201)         DATE 127 (201)           100 Y         EXPECTED         OFTATIND         DEROID         SPAN EAR.         PANS YAL           100 Y         EXPECTED         OFTATIND         DEROID         SPAN EAR.         PANS YAL           100 Y         EXPECTED         OFTATIND         DEROID         SPAN EAR.         PANS YAL           100 Y         EXPECTED         OFTATIND         DEROID         SPAN EAR.         PANS YAL           100 Y         EXPECTED         OFTATIND         DEROID         OFTATIND         DEROID         TOTATIND         DEROID         TOTATIND         DEROID         TOTATIND         DEROID         TOTATIND         DEROID         TOTATIND         DEROID         TOTATIND         DEROID   |                          |  |                        |                |                             | MANUE4CTURER          |
| POINT         EXPECTED         OPTALIND         EROR         PAN LBR.         PAN STAIL           VALUE         CONTINUE         CONTINUE         CONTINUE         CONTINUE         CONTINUE         FORMATION           VALUE         CONTINUE   | R9999.10.19              | 12/10/21   | AV                     | MCS            | 231.06,18                   | PRESTS                |
| 200%         1000 and<br>200%         200% and<br>200% <td>DATE 1210/20<br/>PASSTAIL</td> <td>SPAN ERR.</td> <td></td> <td></td> <td>EXPECTED</td> <td>POINT</td>  | DATE 1210/20<br>PASSTAIL | SPAN ERR.  |                        |                | EXPECTED                    | POINT                 |
| Scott         Difference         Table is an internal interna |                          |  |                        | C TTT I must   |                             |                       |
| Internet         Data         Data         Data         Data           Ais-bit performed by John         Data         Data <td< td=""><td></td><td></td><td></td><td>11.81.00 mm</td><td></td><td></td></td<>   |                          |  |                        | 11.81.00 mm    |                             |                       |
| Arkft preference by: John         Distance         Distance <thdistance< th="">         Distance         Dista</thdistance<>  | .t=l.                    |  |                        | 12 8 12 1 16 1 |                             |                       |
| POINT         EXPECTED         OBTATUD         FRADR         SPASTALL           100 °C         40000 mA         0.0002 mA         0.001 mA         0.001 mA         Pastar           250 °C         60000 mA         2.0020 mA         0.002 mA         0.001 mA         Pastar           300 °C         2.0000 mA         1.0017 mA         0.002 mA         0.001 mA         Pastar           300 °C         2.0000 mA         1.0017 mA         0.002 mA         0.001 mA         Pastar           300 °C         2.0000 mA         2.0000 mA         0.0001 mA         0.001 mA         0.001 mA         9.001 mA         9.001 mA         9.001 mA         9.001 mA         9.001 mA         0.001 mA         9.001 mA         4.001 mA         4.001 mA         9.001 mA         9.001 mA         9.001 mA         4.001 mA         4.001 mA         4.001 mA         9.001 mA         9.001 mA         9.001 mA         4.001 mA         4.001 mA         4.001 mA         4.001 mA         4.001 mA         0.001 mA         10.001 mA </th <th>DATE 12/10/20</th> <th></th> <th></th> <th></th> <th></th> <th></th>  | DATE 12/10/20            |  |                        |                |                             |                       |
| 21:00 °C         50:00 °a         2997 mA         -0.022 aA         -0.011 °c         Pue           10:00 °C         10:00 °mA         10:071 AA         -0.022 aAA         -0.011 °c         Pue           70:07 °C         10:00 °mA         10:071 AA         -0.002 aAA         -0.011 °c         Pue           10:00 °C         10:00 °mA         10:071 °A         -0.002 aAA         -0.002 °AA         -0.001 °AA         -0.011 °c           10:00 °C         10:00 °AA         10:071 °AA         -0.002 °AA         -0.011 °C         Pue           50:07 °C         10:00 °AA         10:977 °AA         -0.021 °AA         -0.011 °C         Pue           20:07 °C         4:000 °AA         10:977 °AA         -0.021 °AA         -0.011 °C         Pue           000 °C         4:000 °AA         4:001 °AA         -0.011 °C         Pue         -0.001 °AA         -0.011 °C         Pue  | PASS/FAIL                |  |                        |                | EXPECTED                    | POINT                 |
| No.0         C         12,000 arX         11,971 arX         4002 arX         0,017 x         Pain           70,0         C         61000 arX         19,979 brA         4002 arX         0,005 arX         Pain           100,0         C         210,000 arX         200,004 arX         0,006 arX         0,005 arX         Pain           100,0         C         210,000 arX         200,004 arX         0,006 arX         0,007 arX         Pain           500,0         C         10,000 arX         12,999 brA         0,007 arX         10,007 ar  |                          |  |                        |                |                             |                       |
| TOY C         L0000 AA         TA999 IAA         -0.0000 IAA         -0.0   |                          |  |                        |                |                             |                       |
| 100.0° C         20000 0A         20000 0A         20000 0A         0.0001 0A         0.  | Pass                     | -0.003%  |                        | 15.9995 mA     | 16,0000 mA                  | 75.00 °C              |
| 75.00°C         16.0000 mÅ         15.9999 mÅ         d*0.001 mÅ         -0.001%         Fina           50.00°C         12.0000 mÅ         11.9977 mÅ         -0.001 mÅ         -0.014%         Fina           25.00°C         16.0000 mÅ         11.9977 mÅ         -0.0021 mÅ         -0.014%         Fina           25.00°C         16.0000 mÅ         1.9979 mÅ         -0.0021 mÅ         -0.015%         Fina           0.00°C         4.0000 mÅ         4.0007 mÅ         -0.001%         Fina         -0.001%   |                          |  |                        |                |                             |                       |
| 50.00 °C         12.0000 mA         11.9977 mA         -0.0021 mA         -0.011%         Pairs           25.00 °C         8.0000 mA         7.9997 mA         -0.0021 mA         -0.011%         Pairs           0.00 °C         4.0000 mA         4.0007 mA         0.0001 mA         -0.0017 mA         -0.011%  |                          |  |                        |                |                             |                       |
| 25.00 °C         8.0000 mA         7.9979 mA         -0.0021 mA         -0.015%         Pase           0.00 °C         4.0000 mA         4.0007 mA         0.0007 mA         0.0007 mA         0.0007 mA         9 ms   |                          |  |                        |                |                             |                       |
| 0.00 °C 4.0002 mA 4.0007 mA 0.0007 mA 0.004% Past   |                          |  |                        |                |                             |                       |
|   |                          |  |                        |                |                             |                       |
|   |                          |  | The last in which have | 107            | o Automa Links              |                       |
|   |                          |  |                        |                |                             |                       |
|   |                          |  | S. 1. 1. 1. 1          |                |                             | 1.4                   |
|   |                          |  |                        | 4              |                             | 1                     |
|   |                          |  |                        |                |                             |                       |
| Management and a second s  |                          |  |                        |                |                             |                       |
|   |                          | Contraction of the local division of the loc | 1.1.1.1.1.1.1.1        |                | 11 14                       | Colored The Colored   |
| DOCUMENT CREATED ON RESPONSIBLE (1)   |                          | -  |                        | IBLE ZO        | ON RESPONS                  | DOCUMENT CREATE       |
| 12/16/19  |                          |  |                        | R              | Provide and a second second |                       |
|   |                          |  |                        | S              |                             |                       |
|   |                          |  |                        |                |                             |                       |

Fig. 54 - Calibration Report Example

# 2.8. Help Desk

MCS-XV calibrator has a video player and documents viewer. These videos can be viewed while a calibration is performed and are designed to assist in the use of the calibrator. Documents can be, for example, calibration procedures or instructions that can be stored and viewed on the calibrator itself.

From the main menu, selecting **HELP** DESK and the tab **VIDEOS** a list of video categories appears. Select the category and the desired video. Press the button **FULL SCREEN** to view the video in full screen and the button **WINDOW** to reduced screen.

To add new videos on the calibrator, connect the USB cable to the computer (type A USB) and to the MCS-XV (Type B USB, see **Figures 02, 04 and 05**, portable, RM and DT versions, respectively). Open **VIDEOS** folder. Copy the new video to any sub-folder (category) of the VIDEOS folder. If you prefer to create a new category, simply create a new folder inside VIDEOS with the name of the desired category and copy the video to this folder.

To insert documents, such as procedures or instructions, files must be converted to PDF and must be saved into the SD-card HELP folder; Create a folder with the name of the document and insert it into this folder.

# **3 - SETTINGS**

The SETTINGS menu has four divisions (tabs at the bottom): DATE AND TIME, NETWORK, SERVICES and SYSTEM.

### 3.1. Date and Time

In **Date and Time** tab is configured the date, time and time zone for the calibrator. You can also set the decimal separator for comma or dot in CSV files.

## 3.2. Network

In the **NETWORK** tab you can configure the calibrator IP address for communication with the computer and Wi-Fi (wireless) network. The IP address can be dynamically configured (**DHCP**) or can be fixed address (Disable DHCP and change desired addresses).

Wifi communication is via USB / WIFI adapter (optional item). In the NETWORK tab you can configure the device name (name which calibrator will be displayed on network). By selecting CONFIGURE WIRELESS (WIFI) the user views available networks and configures which network they want to connect to.

By connecting the calibrator to the network, you can view and print Calibration Reports from your computer. Press network icon to get access to the configured IP address after connecting to the network. When connected to the wireless network, the icon will be Wifi network



Fig. 55 - IP Address

# 3.3. Services

In the SERVICES bar the user can configure the calibrator communication types and other settings. The options are

- REMOTE ACCESS WEBSERVER (Remote Server) and VNC (Virtual Network Computing) access options
- SERIAL COMM Serial Communication Settings
- FILE SHARING AND USB HOST CONTROL Options for allowing / denying file sharing access and setting passwords
- SERVER ADDRESS Remote Server Address Configuration
- **STARTUP MODE** The user selects whether to prefer the calibrator to start in calibrator mode or the main screen.

The types of communication are described below.

# 3.3.1 Web Server

85

To access the calibrator's integrated web server enable the option on the **NETWORK** tab. Connect the calibrator to the network via Ethernet cable or Wi-Fi. To access the web server, open the browser on your computer and enter the following address. To verify the IP address, see figure 56.

<calibrator\_IP\_address>:5000/mcsxvserver/pages/main.cgi User: admin Password: xvmaster



In Web Server, you can monitor the calibrator screen, change the type and value of the output, and read the input signals.

## 3.3.2 Remote access - VNC

Virtual Network Computing (or VNC only) is a desktop graphics sharing system that uses the Remote Frame Buffer protocol (RFB) to remotely control another computer or device. By enabling this option, the calibrator screen can be accessed directly from the computer.

For access via VNC you need to download and install a VNC viewer program, some available for free on the internet. Connect the calibrator to the network via Ethernet or Wifi cable. Set in the VNC viewer the IP address indicated on the network icon (Figure 56) and connect. When prompted, use the password "adm". This password can be changed later on the **NETWORK**> **FILE SHARING AND USB HOST CONTROL** > **SECURITY**.

### 3.3.3 SCPI Command List

To control the calibrator using SCPI commands, connect a serial cable to the MCS-XV Type A USB port (see section 2.1 of this manual, "Part Identification"). Plug the cable into the computer's serial port. In the SETTINGS> NETWORK> SERIAL COMM menu, enable serial communication (RUN switch to  $\bigcirc$ ).

#### **Communication Parameters:**

Parity: none Data bits: 8 Baud rate and Stop Bits: configurable in the SERIAL COMM menu

Below are some examples of MCS-XV calibrator SCPI commands. For complete list contact Presys.

### \*IDN?

**Description:** Instrument identification. **Parameters:** ---**Response:** Manufacturer, ID, Serial Number, Software Version

### \*CLS

Description: Clears the error list. Parameters: ---Response: ---

#### MEASure:PRESsure?

**Description:** Pressure reading **Parameters:** ---**Response:** Pressure reading | unit

## UNIT[:PRESsure]?

Description: Current pressure unit. Parameters: ---Response: Current pressure unit.

#### UNIT[:PRESsure] <unit>

**Description:** Sets the unit of pressure. **Parameters:** New pressure unit **Response:** ---

### SYSTem:ERRor[:NEXT]?

Description: Check the error list. Parameters: ---Response: Last Error

# MEASure[:SCALar]:CURRent[:DC]?

**Description:** mA Input Reading **Parameters:** ---**Response:** mA Input Reading

MEASure[:SCALar]:VOLTage[:DC]?

Description: V Input Reading Parameters: ---Response: V Input Reading

# 3.3.4 System

In the **SYSTEM** tab can be set the volume of the calibrator, the touch screen calibration, identification of the calibrator, language, printer and security options.

#### • Touch Screen Options

To adjust the touch screen, press the **TOUCHSCREEN OPTIONS** button. Press on the screen the places indicated by + (it is recommended to use the stylus for touch screen). After the calibration, press again on the screen at any point. Confirm the calibration to return to SYSTEM Menu.

#### Language Setting

Press the desired language for the system and confirm in OK button. The system must be restarted to save the configuration.

#### Calibrator Identification

In this option is possible to identify your calibrator, choosing a TAG name, Owner name and Location.

#### Sound Options

Press + or - to configure a value for the system audio volume.

#### Screen Brightness

Choose display brightness (25 %, 50 %, 75 %, 100 %).

#### Security Options

The instrument initially has no access password. This setting can be changed in **SECURITY OPTIONS**.

To create a new user, press the key icon and then users icon 2. Fill the blanks and press CREATE. It is possible to add a signature to be used the issuing of a calibration report through the TASK feature. To do so, select the user and press SIGN.

Pay attention to the functions that each user level has access in the following table:

|            | Function     |              |              |                       |              |  |
|------------|--------------|--------------|--------------|-----------------------|--------------|--|
| User Level | Calibrator   | Tasks        | Hart®        | Data-Logger           | Settings     |  |
| Operator   | $\checkmark$ | $\checkmark$ | ×            | ×                     | ×            |  |
| Тес        | $\checkmark$ | ×            | $\checkmark$ | $\checkmark$          | ×            |  |
| Admin      | $\checkmark$ |              | $\checkmark$ | <ul> <li>✓</li> </ul> | $\checkmark$ |  |

To lock the system, press the padlock icon **Settings**  $\rightarrow$  **System** menu. The next time the MCS-XV Calibrator is turned on, it will request login and password. To unlock the system, login as an <u>Admin</u> Level user and press the padlock icon on system menu again.

Never delete all Admin level users when using password access!

### Printer Config

To configure the USB Printer Language (PCL3/PCL5e/PCL3G etc.).

### • Adjust Cal.

Adjustment level protected by password. (See section 4 - Adjustment)

# 4 - Adjustment

# 92

Warning: Enter the following options only after understanding them completely. Otherwise, it may be necessary to return the instrument to the factory for readjustment.

Press ADJUST CAL option from the SETTINGS > System Menu. You should then enter the PASSWORD <u>9875</u> to access the adjustment menu.

The password functions as a protection to adjustment ranges. After the password is entered the menu displays the options **GENERAL**, **INPUTS** and **OUTPUTS**. In the option **General** you can Recover the Manufacturer Adjustment backup file and change the last calibration date if a new adjustment is done.

For the adjustment, choose between inputs, outputs and pressure adjustment (General Tab).

| Adjustment Backup/Reco<br>Restore<br>Calibration info<br>Last calibration:<br>Cal. interval(months): | very<br>Friday, November<br>12 | Pressure adjust | Inputs adjustment<br>V<br>mV.G1<br>mV.G2<br>mV.G3<br>mV.G4<br>mA | PRESS START |              | Outputs adjustment<br>V<br>mV<br>mA<br>OHM-400<br>OHM-2500<br>CJC | O.OOO<br>STEP1 STEP2 STEP3 S | TEP4 |
|--|--------------------------------|-----------------|--|-------------|--------------|---|------------------------------|------|
|  |                                | Save date       | V_Ohm3<br>V_Ohm4<br>Ohm1<br>Ohm2<br>Ohm3<br>CJC                  | 0           | PNT1<br>PNT2 | PROBE_V1<br>PROBE_V2<br>PROBE_R1<br>PROBE_R2                      | 0 SAV                        | /E   |
| General  | Inputs                         | Outputs         | General  | START       | Outputs      | General   | START<br>Inputs Output       | ts   |

Fig. 57 - Adjustment Options

Note that the thermocouples will only be adjustment after the **mV** and cold junction (CJC) adjustment have been performed. Only in case of OHM or RTD, you have to perform the **mV** adjustment first.

# 4.1. Input adjustment (IN)

### 1) mV, V, mA Inputs

Select the corresponding mnemonic and press START button. Apply the signals presented in the tables below.

Note that the applied signals just need to be close to values shown in the table.

Once the signal has been applied, store the values of the 1<sup>st</sup> and 2<sup>nd</sup> calibration points (PNT1 and PNT2).

| mV Input | PNT1      | PNT2       |
|----------|-----------|------------|
| G_4      | 0.000 mV  | 70.000 mV  |
| G_3      | 0.000 mV  | 120.000 mV |
| G_2      | 0.000 mV  | 600.00 mV  |
| G_1      | 600.00 mV | 2400.00 mV |

| V Input      | PNT1     | PNT2      |
|--------------|----------|-----------|
| Single range | 0.0000 V | 11.0000 V |

| mA Input     | PNT1      | PNT2       |
|--------------|-----------|------------|
| Single range | 0.0000 mA | 20.0000 mA |

### 2) OHMS Input

Input adjustment for  $\Omega$  is performed in two steps:

### a) Application of mV Signal:

For the adjustment below, leave terminals RTD3(+) and RTD4(+) short-circuited

| mV Signal | Terminals              | PNT1             | PNT2       |
|-----------|------------------------|------------------|------------|
| V_OHM3    | RTD3(+) and GND IN (-) | 70.000 mV        | 120.000 mV |
| V_OHM4    | RTD4(+) and GND IN (-) | <b>70.000</b> mV | 120.000 mV |

# b) Application of Resistance:

Connect a decade-box or standard resistors on terminals RTD1, RTD2, RTD3 and RTD4 (4-wire connection).

| Γ | resistors | PNT1      | PNT2       |
|---|-----------|-----------|------------|
|   | OHM3      | 20.000 Ω  | 50.000 Ω   |
|   | OHM2      | 100.000 Ω | 500.000 Ω  |
|   | OHM1      | 500.000 Ω | 2200.000 Ω |

#### 3) CJC Adjustment

Measure the temperature of input terminal GND IN and store only one point.

| Cold Junction | PNT1                   |
|---------------|------------------------|
| CJC           | 32.03 °C               |
|               | (measured temperature) |

### 4.2. Output Adjustment (OUT)

The output adjustment (except for CJC and Probe) is performed in STEPS. For each STEP the calibrator outputs a signal of the same type selected which must be measured and stored.

### 1) V, mV and mA Outputs

For these output ranges, the display shows three buttons: **STEP1**, **STEP2** and **STEP3**. Select **STEP1**. The signal generated should be measured by a standard and the value must be stored, by pressing **SAVE** button. Repeat the procedure for **STEP2** and **STEP3**.

#### 2) OHM Output


Due to accuracy reasons, the resistance output must be measure by a standard using 4-wire connection. Initially, the polarity of the wires is not important as the excitation current can flow in one or the other direction - from RTD1 to RTD2 terminal or from RTD2 to RTD1 terminal.

The adjustment should be performed for both ranges: 400  $\Omega$  (OHM-400) and 2500  $\Omega$  (OHM-2500).

For these output ranges, the display shows four buttons: **STEP1**, **STEP2**, **STEP3** and **STEP4**. Select **STEP1**. The signal generated should be measured by a standard and the value must be stored, by pressing **SAVE** button. Repeat the procedure for **STEP2** and **STEP3**. Change the plugs connected to RTD1 terminal with the ones connected to RTD2 terminal and select **STEP4**. Measure the signal generated and store the standard value.

#### 3) Probe Adjustment

First identify the connector pins for **Probe** input according to the figure below.



The **PROBE** adjustment is performed in two steps:

# a) Application of mV Signal:

| mV Signal | Terminals | Bornes      | PNT1      | PNT2       |
|-----------|-----------|-------------|-----------|------------|
| V_2       | RTD2(+)*  | GND OUT (-) | 70.000mV  | 120.000 mV |
| V_1       | RTD2(+)*  | GND OUT (-) | 120.000mV | 600.00 mV  |

(\*) RTD2, for **PROBE** adjustment, refers to the drawing shown in Figure 58. If required, you can purchase a connector adapter with J121 (female) terminals to ease the adjustment. Order code: 06.07.0017-00.

### b) Application of Standard Resistors:

Connect a decade box or standard resistor to the probe connector, at positions RTD1, RTD2, RTD3 and RTD4, as shown in Figure 54.

| resistors | PNT1      | PNT2      |
|-----------|-----------|-----------|
| R_2       | 20.000 Ω  | 50.000 Ω  |
| R_1       | 100.000 Ω | 500.000 Ω |

# 4) CJC Adjustment

The adjustment of the cold junction related to the thermocouple output is similar to the one related to the thermocouple input. But the temperature should be taken at the GND OUT terminal.

### 4.3. Pressure Calibration

By pressing **Pressure Adjust** in the General Tab, there are 3 options: **mV ADJUSTMENT**, **PRESSURE ADJUSTMENT** and **PARAMETERS CONFIGURATION**. Enter the **PRESSURE ADJUSTMENT** option.

The calibration of the sensors consists of the application of at least two pressure values: one close to the minimum range value and the other on the full scale (FS) of the pressure sensor.

The number of adjustment points can be increased in **CONFIGURE POINTS** depending on the pressure sensor.

| START STOP        |
|-------------------|
| Patanti alter     |
| 0.2 psi<br>.0 psi |
| CONFIGURE POINTS  |
| o psi<br>o psi    |
| VE                |
| )<br>(            |

Fig. 59 - Pressure Adjustment


Select a pressure sensor between C1, C2, C3 and C4. Press START. Choose an adjustment point and verify the pressure value to be applied. Apply the pressure and press SAVE button to type the pressure value.

# 5 - Maintenance

# 5.1. Replacing Battery (only for MCS-XV Portable)

To change the MCS-XV battery, proceed as follows:

- Loosen the screws on the battery cover as shown in figure 60 (A);
- Disconnect the battery and pull it, see figures 60 (B) and (C);
- Insert the new battery and connect it, as shown in figure 60 (D);
- Close the lid, see figure 60 (E).




# 5.2. Replacing Current Input Fuse

To replace the current fuse of MCS-XV, proceed as follows:

- Rotate the fuse holder counterclockwise, as shown in figure 61 (A). Try to use a plastic tool to avoid damaging the fuse holder;

- The fuse holder will be released, as shown in 61 (B);
- Pull the fuse holder and remove the fuse, see figure 61 (C);
- Place the spare fuse. The fuse is in the carrying case;



# 6 - Pressure Units Conversion

| psi | bar        | mbar               | mPa                 | kPa                |
|-----|------------|--------------------|---------------------|--------------------|
| 1   | 0.06894757 | 68.94757           | 0.006894757         | 6.894757           |
|     |            |                    |                     |                    |
| psi | Pa         | atm                | at                  | mmH₂O@4°C          |
| 1   | 6894.757   | 0.06804596         | 0.07030695          | 703.0890           |
|     |            |                    |                     |                    |
| psi | cmH₂O@4°C  | ftH2O@4°C          | inH₂O@4°C           | inH₂O@60°F         |
| 1   | 70.30889   | 2.306726           | 27.68067            | 27.70759           |
|     |            |                    |                     |                    |
| psi | torr       | mmHg@0°C           | cmHg@0°C            | inHg@0°C           |
| 1   | 51.71507   | 51.71507           | 5.171507            | 2.036026           |
|     |            |                    |                     |                    |
| psi | inHg@60°F  | gf/cm <sup>2</sup> | kgf/cm <sup>2</sup> | kgf/m <sup>2</sup> |
| 1   | 2.041772   | 70.30695           | 0.07030695          | 703.0695           |

## Notes

- 104
- Adjusting procedures for MCS-XV must be performed under the reference conditions of temperature and humidity.
- Better calibration results are achieved if warm-up time is at least two hours and if the battery charger remains disconnected from the calibrator since one hour before its usage.
- The standards used to adjust MCS-XV should have accuracy at least 3 times better than the accuracy values provided in this manual.

**PRESYS** | Instruments Inc. www.presys.com.br